, ,		· · · · ·
Subnut I Copy To Appropriate District State of New Mexico		Form C-103
		Revised August 1, 2011 WELL API NO.
District II - (575) 393-6161     HOBBS OCD       1625 N. French Dr., Hobbs, NM 88240     BBS OCD       District II - (575) 748-1283     OIL CONSERVATION DIVISION       811 S. First St., Artesia, NM 88210     OIL CONSERVATION DIVISION       District III - (505) 334-6178     MAR 3 0 2012       1000 Rio Brazos Rd., Aztec, NM 87410     Santa Fe, NM 87505		30-025-37175
		5. Indicate Type of Lease
		STATE FEE X   6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NMECEIVED		6. State Off & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		
		T D Pope 35
1 Type of Well Oil Well $\overline{\mathbf{X}}$ Gas Well $\Box$ Other		8. Well Number 3 -
2. Name of Operator Celero Energy II, LP		9. OGRID Number
Celero Energy II, LP		247128 10. Pool name or Wildcat
3. Address of Operator <sub>400</sub> W. Illinois, Ste. 1601 Midland, TX 79701		
Midland, TX 79701 Denton; Devonian   4. Well Location ()		
Unit Letter G : 1505 feet from the N line and 2120 feet from the <u>E</u> line		
Section 35 Township 14S Range 37E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to	o Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBS		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR		
PULL OR ALTER CASING DOWNHOLE COMPL		Т ЈОВ 🗌
OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
2/28 - 3/7/2012 RIH w/ 7" CIBP & set at 12490'. RIH w/ WL, correlate to Schlumberger GR/CCL/CNL dated 6/30/05, perf Devonian intervals w/ 4'		
HSCCG loaded at 2 SPF - 180 degree phasing as follows: 12406' - 12420' 30 shots, 12380' - 12394' 30 shots, 12259' - 12265' 14		
shots, 12236' - 12244' 18 shots, 12182' - 12200' 36 shots, 12165' - 12175' 22 shots, 12147' - 12153' 14 shots, 12057' - 12086' 60		
shots. RIH with 4" bailer, dump bail 10' of cmt on top of CIBP at 12490'. Pkr at 12295'. Acidize perfs 12360' - 12460' w/ 7000 gal of inhibited 15% NEFE HCL containing 5% xylene. POOH w/ pkr. PU 7" Kline RBP, retrieving tool, 7" Kline packer, 2 3/8 Std SN, x-		
over. RIH with 384 jts of 2 7/8 tbg. Set RBP at 12230'. PU 1 jt of tbg & set pkr at 12295'. Load tbg w/ 27 BFW, test RBP to 1500#,		
held. Try to load csg, pump 200 BFW, unable to load, release pkr. POH & set pkr at 11990'. Load backside with 45 bbls water,		
pressure up to 450#, heldk. Load tbg with 27 BFW, establish inj rate of 2.2 BPM at 3000#. Acidize perfs 12057' - 12265' w/ 13986 gal of inhibited 15% NEFE HCL containing 5% xylene. Release pkr. RIH to retrieve RBP, unable to latch up, pump 100 BFW down		
tbg to wash off RBP. Latch up, unable to release, get off RBP. POH w/ all 2 7/8 tbg, pkr & retrieving tool. PU RBP retrieving tool,		
jars, BS, 4) 3 1/2 DC's, x-over. RIH with 379 jts of 2 7/8 tbg, latch on to RBP. RU power swivel to hold torque, jar RBP loose. POH w/ all 2 7/8 tbg & equip, left RBP in hole. *Continued on attached sheet		
w/ an 2 //8 tog & equip, left KBF in hole. Continued		
Spud Date:	Rig Release Date:	
I have be and for that the information of any internal		
I hereby certify that the information above is true and con	ipiele to the best of my knowledg	je and bener.
SIGNATURE Lisa Arm t		DATE 02/25/2012
SIGNATURE CILSA I CANCI	TITLE Regulatory Analyst	DATE <u>03/27/2012</u>
	E-mail address: <u>lhunt@celeroene</u>	PHONE: (432)686-1883
For State Use Only		
	TITLE STATE ME	72 DATE 7-2-2012
Conditions of Approval (if any):		ADP 11 2 2012
/ -		IDD II & LUIT

APR U 2 2017

TD Pope 35 #3 – C103 continued

5

3/9/12 - PU 7" RBP retrieving tool. RIH w/ 128 jts of 2 7/8" tbg to RBP, latch on to RBP. POH w/ all 2 7/8" tbg, retrieving tool & RBP. LD 26 jts of 2 7/8" tbg.

3/12/12 - RU power cable spooler, PU GE sub pump as follows: 1) stainless smartguard, 2) TR5 – 92 180Hp 1275V 89A motors, 1) TR5 2BP 2L HSS seal, 1) TR4 Mag 2 gas seperator, 5) TD1750 pumps - 625 stages, 1) 2 3/8 Std S.N., x-over, 245 jts of 2 7/8 6.5# L-80 8rd tbg (7924.27'), x-over 10 jts of 2 7/8 PH-6 tbg,

3/13/12 - RIH with total of 125 jts of 2 7/8" PH-6 tbg (3924.41'). Splice lower pigtail into NEW # 2 flat lead cable, land donut into seaboard wellhead, WIR – 108000. NDBOP. Build WH, set up drive, check rotation, start pumps up at 60 Hz straight frequency & pumped up in 16 min. RD.

ı