State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-07526	
<u>DISTRICT II</u>	2	,	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410			180201 100	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			NORTH HOBBS (G/SA) U	NIT
Type of Well: Oil Well	Gas Well Other (Gas Injector	8. Well No. 112	V
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.				
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM	1 88240 505/397-8	3200	1 11881 11881	
4. Well Location				
Unit Letter E : 1370	Feet From The NORTH	330 Fee	t From The WEST	Line -
Section 32	Township 18-S	Range 38-F	NMPM	LEA County
	11. Elevation (Show whether DF, RKE 3642 DF	R, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check NOTICE OF INTE	Appropriate Box to Indicate Nat ENTION TO:		er Data SEQUENT REPORT OF	:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS	S. PLUG & AE	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMENT	JOB	
OTHER: Repair casing leak	X	OTHER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. Pull equipment.			23456789101	•
2. Run new liner across bad casing.			N. 20 100 101	17273
3. Perforate 4114-4220			/ B**	\ \ \
4. Acid stimulate and run production equipment.				
4. Acid stillulate and full production ec	quipment.		1 10 m	, FS
4. Acid stimulate and run production ec	quipment.		and and	93
4. Acid stimulate and full production ec	quipment.		and and	A1516171
4. Acid simulate and full production ec	quipment.		and and	93
4. Acid stillulate and full production ec	quipment.		Sold Sold Sold Sold Sold Sold Sold Sold	93
4. Acid simulate and full production ed	quipment.		and and	93
4. Acid simulate and full production ed	quipment.		and and	93
I hereby certify that the information above is true a	nd complete to the best of my knowledge a		or below-grade tank has been/will be	N61778)
I hereby certify that the information above is true at closed according to NI/IOCD guidelings		or an (attached) alternative	or below-grade tank has been/will be OCD-approved plan	constructed or
I hereby certify that the information above is true as closed according to NMOCD guidelings SIGNATURE	nd complete to the best of my knowledge a		or below-grade tank has been/will be OCD-approved plan risor DATE	constructed or 3-28-05
I hereby certify that the information above is true as closed according to NMOCD guidelings SIGNATURE TYPE OR PRINT NAME David Nelson	nd complete to the best of my knowledge a	or an (attached) alternative	or below-grade tank has been/will be OCD-approved plan	constructed or
I hereby certify that the information above is true as closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME David Nelson For State Use Only	nd complete to the best of my knowledge a , a general permit E-mail address:	or an (attached) alternative	or below-grade tank has been/will be OCD-approved plan risor DATE	constructed or 3-28-05

CONDITIONS OF APPROVAL IF ANY: