State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATION	DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		VELL API NO. 30-025	-28884
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		BACK TO A	NORTH HOBBS (G/SA) UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 29	
Type of Well:		8	8. Well No. 342	
Oil Well Gas Well Other Injector				
Name of Operator Occidental Permian Ltd.		~ (9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200				
4. Well Location				/
Unit Letter O : 1230	Feet From The SOUTH	Feet Fr	rom The EAST	Line -
Section 29	Township 18-S	Range 38-E	NMPM	LEA County
	11. Elevation (Show whether DF, RKB, RT GR, e 3646 GR	etc.)		
Pit or Below-grade Tank Application	or Closure			
	1 1	. 11	D'	- .c
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume bbls	; Construction Mater	ial	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA	AL WORK	X ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT			
==			<u>=</u>	
PULL OR ALTER CASING	Multiple Completion CASING TEST AND CEMENT JOB			
OTHER:	OTHER:	·		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1 DIDII Duli Infection confirm				
 RUPU. Pull Injection equipment. Sqz csg leak from 3994-4052' with 200 sx Prem + cmt w/3% CaCl. *** Also had cmt across perfs @4072-4148'. 				
 Sqz csg leak from 3994-4052' with 200 sx Prem + cmt w/3% CaCl. *** Also had cmt across perfs @4072-4148'. Perforate dthe following intervals; 4083, 89, 4100, 06, 36, 42, 48, 73, 81, 89, 97, 4216, 42, and 4244', using 2 spf, 120 deg ph. (28 holes). 				
4. Stimulate perfs 4083-4250 w/1200 g 15% PAD acid.				
5. Re-Sqz perfs @3994-4052 with 100 sx Prem + cmt w/3% CaCl.				
6. RIH w/5.5" Guiberson UNI VI pc pkr, XL on/off tool w/1.875 ss "F" nipple, 131 jts 2-7/8" Duoline tbg. Pkr set @4054'.				
7. Load csg w/110 bbl pkr fluid.	1st csg to 520 psi for 30 min and chart for the N	IMOCD. RDPU. Cl	ean Location.	
				122
Rig Up Date: 03/19/2005				
Rig Down Date: 04/07/2005				100
Therefore and a second of the second		-1:-C TC1		7-A 1
I hereby certify that the information above constructed or	is true and complete to the best of my knowledge and be	eliel. I further certify tha	it any pit or below-grade tank h	nas been/will be
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved				
	plan	,	1	10 PM
SIGNATURE	TITLE	Workover Comple	etion Specialist DATI	E 04/08/2005
TYPE OR PRINT NAME Robert Gi		gilbert@oxy.com	TELEPHONE NO.	
For State Use Only	a man and a second a			
	alling of bistr	ICT SUPERVISOR,	GENERAL MANAGER	on delan lan
APPROVED BY	XIII OC MILE		DA	11 7/22/05
CONDITIONS OF APPROVAL IF ANY:				

