Submit I Copy To Appropriate District Office  State of New Mexico Minerals and Natural Resources	Form C-103
District 1 – (575) 393-6161 Energy, Witherars and Waterar Resources	Revised August 1, 2011 WELL API NO.
District II - (575) 748-1283 APR 1900 NEED VATION DIVISION	30-025-35638
811 S First St., Artesia, NM 88210  District III – (505) 334-6178  1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 <u>District IV</u> – (505) 476-3460  Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505	or state on a sub zouse rich
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	Owen "B"
1. Type of Well: Oil Well Gas Well Other	8. Well Number 10
2. Name of Operator Apache Corporation	9. OGRID Number 873
3. Address of Operator	10. Pool name or Wildcat
303 Veterans Airpark Lane, Ste 3000, Midland TX 79705	Penrose Skelly; GB/Blinebry O&G (Pro Gas)
4. Well Location M 1137 South	West
Unit Letter : feet from the line and	feet from theline
Section 34 Township 21-S Range 37-E  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	Table 112
3 444'	Se office and the
į turį.	· .
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	<del>_</del>
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN' DOWNHOLE COMMINGLE	I JOB
_	
OTHER: OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
3/23/12 Notify Mark (ACD) of Dra intent 3/26/12 MIDN 2/27/12 mag CIDD 6 FE20! Circ :/MID to 2700!	
3/23/12 Notify Mark (OCD) of P&A intent. 3/26/12 MIRU 3/27/12 Tag CIBP @ 5529'. Circ w/MLF to 3700' Spot 25 sx class "c" cmt from 5188'-4938' Tag Toc @ 4892'. 3/28/12 Set CIBP @ 3700' RIH tag CIBP @ 3700'	
Test casing to 500 PSI. Circ well w/85 bbls MLF spot 40 sx class "c" cmt 3700'-329 Spot 25 sx class "c"	
cmt 2600'-2350'. 3/29/12 Tag Toc 2350'. Spot 25 sx class "c" cmt 1180'-930' Tag Toc @ 935'. Perf @ 250'	
Sqz 80 sx class "c" Circ cement behind all casings. Rig down all P&A equipment. Cutoff well head, anchors clean location. Install dry hole markers	
Approved for plugging of well bore only.	
Liability under bond is retained pending receipt of	
C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Borgs under	
which may be found at OCD web Fage under	
Forms, www.emnrd.state.nm.us/ocd	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Manager	0/00/40
SIGNATURE Manager TITLE	DATE 3/30/12
Type or print name E-mail address:	PHONE: 432-561-8600
For State Use Only	
APPROVED BY STATE STATE STATE STATE STATE NAS	DATE 4-10-2012
Conditions of Approval (if any):	DAIL 4-10-CO/L