Office	s To Áppropriate Distri		State of New				Fo	rm C-103
District I	a 9 <i>a</i>	Ener	rgy, Minerals and Natural Resources			WELL ADINO		une 19, 2008
District II  District II  NA STATE OF A PROPERTY AND S						WELL API NO. 30-025-10214	. /	
1301 W. Grand	Ave., Artesia, NM 882	2 2 2 2 2 2 2 2 2			ION	5. Indicate Type	e of Lease	
District III 1000 Rio Brazo	s Rd., Aztec, NM 8741	R 1 0 2012	1220 South St.		1	STATE	☐ FEE	$\boxtimes$
District IV	cis Dr., Santa Fe, NM		Santa Fe, NN	VI 8/303		6. State Oil & C	Gas Lease No.	
87505		RECEIVED						
(DO NOT LIGE			REPORTS ON WE		то л	7. Lease Name	or Unit Agreem	ent Name
DIFFERENT R			R PERMIT" (FORM C-10		10 A	Lou Worthan	,	
PROPOSALS.)	Vell: □Oil Well	⊠/Gas Well	Other:		•	8. Well Numbe	r 005	
2. Name of		7				9. OGRID Num	nber	
Apache Corp		<u>/</u>				873		
3. Address of	•	to 2000 Midlan	d TV 70705			10. Pool name of Blinebry O& G (F		
4. Well Loc	Airpark Lane, Suit	te 3000 ivildian	Id, 1X 79705		İ	Billiebry O& G (F		
	ation t Letter C	: 660	feet from the North	ı lin	e and 1980	) feet fr	om the West	line
	tion 11	000	Township 22S	Range 37E		NMPM	County Lea	
Sec.	HOII 11	11. Elev	ation (Show whether				County ===	
T	Section 1997	3353' GL						
	12. Chec	ck Appropria	ite Box to Indicat	te Nature of	f Notice, I	Report or Othe	er Data	
	NOTICE OF	INTENTIO	N TO:	1	SUBS	SEQUENT RI	EPORT OF:	
PERFORM F	REMEDIAL WORK		ND ABANDON 🔲	REMED	DIAL WORK		ALTERING C	
TEMPORAR	ILY ABANDON		E PLANS			LLING OPNS.	P AND A	
	TER CASING	_	LE COMPL	CASING	G/CEMENT	JOB 🗆		
DOWNHOLE	COMMINGLE							ę
OTHER:			П	OTHER	R: CO & ACI	DIZE		×
12 Doca								
			tions. (Clearly state	all pertinent	details, and			stimated date
of sta	arting any proposed		tions. (Clearly state RULE 1103. For M	all pertinent	details, and			stimated date
of sta	arting any proposed completion.	d work). SEE 1		all pertinent	details, and			stimated date
of sta	arting any proposed	d work). SEE 1		all pertinent	details, and			stimated date
of sta or red Apache pe 3/13/2012	arting any proposed completion. erformed the follow MIRUSU	d work). SEE I		all pertinent	details, and			stimated date
of sta or rea Apache pe 3/13/2012 3/14/2012	arting any proposed completion. erformed the follow MIRUSU POOH w/rods & t	d work). SEE I	RULE 1103. For M	all pertinent	details, and			stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012	arting any proposed completion. erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg.	d work). SEE I	RULE 1103. For M	all pertinent	details, and			stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/22/2012	arting any proposed completion. erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'.	d work). SEE I ring: bg vn due to parafi	RULE 1103. For M	all pertinent	details, and			stimated date
of sta or rea Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/22/2012 3/23/2012	arting any proposed completion. erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg.	d work). SEE I ring: bg vn due to paraff circ.	RULE 1103. For M	all pertinent	details, and			stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; bailer RIH w/packer to 4	d work). SEE I	RULE 1103. For M	all pertinent ultiple Compl	details, and			stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/23/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; bailer RIH w/packer to 4 Acidize Blinebry w	d work). SEE I	RULE 1103. For M fin. t; release packer. acid & 2850# Rock	all pertinent ultiple Compl	details, and			stimated date
of sta or rea Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/23/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; bailer RIH w/packer to 4	d work). SEE I	RULE 1103. For M fin. t; release packer. acid & 2850# Rock	all pertinent ultiple Compl	details, and			stimated date
of sta or rea Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/23/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro	d work). SEE I	RULE 1103. For M fin. t; release packer. acid & 2850# Rock	all pertinent ultiple Compl	details, and			stimated date
of sta or rea Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/23/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro	d work). SEE I	RULE 1103. For M fin. t; release packer. acid & 2850# Rock	all pertinent ultiple Compl	details, and			stimated date
of sta or red Apache per 3/13/2012 3/14/2012 3/15/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/28/2012 3/29/2012	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; bailer RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/proposed RIH w/pump & roce RIH w/p	d work). SEE I	Fin.  t; release packer. acid & 2850# Rock  5775'.	all pertinent ultiple Compl	details, and etions: Att			stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012 3/29/2012 Spud Date:	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/prog RIH w/pump & rod 02/20/1996	d work). SEE I	RULE 1103. For M fin. d; release packer. acid & 2850# Rock @ 5775'.	sall pertinent ultiple Compl Salt.	details, and etions: Att	ach wellbore diag		stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012 3/29/2012 Spud Date:	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/prog RIH w/pump & rod 02/20/1996	d work). SEE I	Fin.  t; release packer. acid & 2850# Rock  5775'.	sall pertinent ultiple Compl Salt.	details, and etions: Att	ach wellbore diag		stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012 3/29/2012 Spud Date:	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/prog RIH w/pump & rod 02/20/1996	d work). SEE I	FILE 1103. For M  Fin.  It; release packer.  acid & 2850# Rock  © 5775'.  Rig Release	Salt.  Se Date: 02	details, and etions: Att	ach wellbore diag		stimated date
of sta or red Apache pe 3/13/2012 3/14/2012 3/15/2012 3/16/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012 3/29/2012 Spud Date:	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro RIH w/pump & rod 02/20/1996	d work). SEE I	FILE 1103. For M  Fin.  It; release packer.  acid & 2850# Rock  © 5775'.  Rig Release	sall pertinent ultiple Compl Salt.	details, and etions: Att	ach wellbore diag		stimated date d completion
of sta or red Apache per 3/13/2012 3/14/2012 3/15/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/28/2012 3/29/2012 Spud Date:	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro RIH w/pump & rod 02/20/1996	d work). SEE I	fin.  d; release packer. L acid & 2850# Rock @ 5775'.  Rig Release  ue and complete to t	Salt.  Se Date: 02/	details, and etions: Att	e and belief.	DATE 04/03/20	stimated date d completion
of sta or rea Apache pe 3/13/2012 3/14/2012 3/15/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/29/2012 Spud Date:	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; baile RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro RIH w/pump & rod 02/20/1996  Ty that the information of the complete RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro RIH w/pump & rod 02/20/1996	d work). SEE I	fin.  d; release packer. L acid & 2850# Rock @ 5775'.  Rig Release  ue and complete to t	Salt.  Se Date: 02	details, and etions: Att	e and belief.	gram of propose	stimated date d completion
of sta or red Apache per 3/13/2012 3/14/2012 3/15/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/29/2012 Spud Date: I hereby certif SIGNATURE	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; bailer RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro RIH w/pump & rod 02/20/1996  That the information of the conty	d work). SEE I	fin.  d; release packer. L acid & 2850# Rock @ 5775'.  Rig Release  ue and complete to t	Salt.  Se Date: 02/ he best of my  r. Staff Engr T  dress: Reesa.	details, and etions: Att	e and belief.  hecorp.com	DATE 04/03/20 PHONE: 432/81	stimated date d completion
of sta or red Apache per 3/13/2012 3/14/2012 3/15/2012 3/22/2012 3/23/2012 3/24/2012 3/26/2012 3/27/2012 3/28/2012 3/29/2012 Spud Date:	arting any proposed completion.  erformed the follow MIRUSU POOH w/rods & t Cannot swab dow Hot oil tbg. Tag fill @ 5762'. Could not break of RIH w/bailer; bailer RIH w/packer to 4 Acidize Blinebry w Swab. RIH w/pro RIH w/pump & rod 02/20/1996  That the information of the conty	d work). SEE I	fin.  d; release packer. L acid & 2850# Rock @ 5775'.  Rig Release  ue and complete to t	Salt.  Se Date: 02/	details, and etions: Att	e and belief.  hecorp.com	DATE 04/03/20	stimated date d completion