Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103 Revised August 1, 2011
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N French Dr., Hobbs (188240 District II – (575) 748-1289 OH GONGERNA TION DIVISION	WELL API NO.
811 S First St., Artesia, NM 88210 a School CONSERVATION DIVISION	30-025-06598 5. Indicate Type of Lease
District III - (505) 334-6178	STATE FEE
1000 Rio Brazos Rd , Aztec, NW 87410 <u>District IV</u> – (505) 476-3460 1220 S St Francis Dr , Santa Fe, NM SAND REPORTS ON WELLS	6. State Oil & Gas Lease No.
SUNDAT NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	Warlick, L.G. "C"
1. Type of Well: Oil Well Gas Well Other	8. Well Number
2. Name of Operator V Apache Corporation	9. OGRID Number 873
3. Address of Operator	10. Pool name or Wildcat
303 Veterans Airpark Lane, Ste 3000, Midland TX 79705	Penrose Skelly; Grayburg
4. Well Location Unit Letter O : 405 South South South South Geet from the South Continue Continue South Geet from the South South Continue Continue South South Continue Continue South South	
Section 15 Township 21-S Range 37-E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc., 341666	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI	
TEMPORARILY ABANDON	_
DOWNHOLE COMMINGLE	_
OTHER: OTHER	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
	,
4/4/12 Notify Mark (OCD) of P&A intent. 4/5/12 MIRU Tag CIBP @ 4218'.	Spot 55x class c" cmt.
4/6/12 Tag toc @ 3827' RTH/set CTRD 5 1/2 @ 3680' DIW tag CTRD @ 3690'	
4/9/12 Test casing to 500 PSI. Hold 15 min ok. Circ well 85 bbls MLF. Spot 25x class c. from 3680'-3431'. Perforate @ 2852'. Sqz 130x class c. Woc 4 hrs RIH tag toc @ 2344'	
RUWL trk RIH perforate @ 1235'.	
4/10/12 Sqz 35x class c cmt from 1235' to 1135' woc 4 hrs,RIH tag toc @ 11 RIH perforate @ 355' sqz 100x class c to surface. RDMD all Pa wellhead, anchors and clean location. Install dry hole, marker.	XA equip. Cutoff
wellhead, anchors and clean location. Install dry hole marker.	
A	pproved for plugging of well bore only.
Is	idbility under hand is retained pending receipt FC:103 (Bubsequent Report of Well Plugging)
Spud Date: Rig Release Date: W	hich may be found at OCD Web Page under 37915, www.enurd.xtate.nm.us/ocd.
	State with the state of the sta
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE Manager	DATE 4/10/12
Type or print name Bagley E-mail address:	PHONE: 432-561-8600
For State Use Only	
APPROVED BY: A COMPLETE STATE NOT	DATE 4-25-2012
Conditions of Approval (if any):	DATE 1-03- CUIL