Form 3160-5 (March 2012)

## OCD-HOBBS

**UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS

of use this form for proposals to deriver the sum of the sum o

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. NMNM67111 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/A	greement, Name and/or No.	
1. Type of Well			1		
✓ Oil Well Gas W	/ell / Dther		8. Well Name and GERONIMO FEI		
2. Name of Operator WAGNER OIL COMPANY			9. API Well No. 30-025-32133	1100	
3a. Address		3b. Phone No. (include area c		or Exploratory Area	
500 COMMERCE, SUITE 600 FORT WORTH, TEXAS 76102		817-335-2222	GERONIMO;DE	LAWARE Tonto, Yates	
4. Location of Well (Footage, Sec., F.R., M., or Survey/Description) 2275' FSL & 960' FWL OF SECTION 31; T-9-S, R-33-E			11. County or Pari		
22/5 FSL & 980 FWL OF SECTION 31, 19-3, 18-35-2			LEA COUNTY, N	NEW MEXICO .	
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NATUI	OF NOTICE, REPORT OR O	THER DATA	
TYPE OF SUBMISSION		Т	PE OF ACTION	· · · · · · · · · · · · · · · · · · ·	
✓ Notice of Intent	✓ Acidize	Deepen	Production (Start/Resume	) Water Shut-Off	
	Alter Casing	✓ Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
	Change Plans	Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	er Disposal	
the proposal is to deepen directional Attach the Bond under which the w	ally or recomplete horizontally or recomplete horizontally ork will be performed or project operations. If the operation hotices must be an administration of the operation of t	y, give subsurface locations and vide the Bond No. on file with on results in a multiple completi	neasured and true vertical depth LM/BIA. Required subsequent nor recompletion in a new inter	work and approximate duration thereof. If is of all pertinent markers and zones. reports must be filed within 30 days wal, a Form 3160-4 must be filed once een completed and the operator has	
Abandon existing perfs w/CIBP, perf	, frac and evaluate Yates	sand intervals 2953' - 3120'.			
Set CIBP @ 4830' w/20' cmt on top Set CIBP @ 3350' w/20' cmt on top Test csg & plug 3000 psi Set cmt retainer @ 3050', cmt 5 1/2 : Drill out retainer & cmt, test 1000 psi		Jbee	COP 9-15		

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Title Regulatory Analyst			
te 04/17/2012 APPROVED			
L OR STATE OFFICE USE			
Title / A Date			
WESLEY W. INGRAM PETROLEUM ENGINEER			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Perf Yates intervals 2953' - 3120' TIH w/ 2 7/8 tbg & pkr, set pkr @ 2800'

Put well to production

Frac Yates intervals w/300,000# 20/40 sand

Acidize Yates intervals w/2000 gal 7-1/2% HCI + ball sealers

Geronimo Federal 9 30-025-32133 Wagner Oil Company April 20, 2012 Conditions of Approval

## Timing Limitation Stipulation / Condition of Approval for lesser prairie-chicken:

Oil and gas activities including 3-D geophysical exploration, and drilling will not be allowed in lesser prairie-chicken habitat during the period from March 1st through June 15th annually. During that period, other activities that produce noise or involve human activity, such as the maintenance of oil and gas facilities, pipeline, road, and well pad construction, will be allowed except between 3:00 am and 9:00 am. The 3:00 am to 9:00 am restriction will not apply to normal, around-the-clock operations, such as venting, flaring, or pumping, which do not require a human presence during this period. Additionally, no new drilling will be allowed within up to 200 meters of leks known at the time of permitting. Normal vehicle use on existing roads will not be restricted. Exhaust noise from pump jack engines must be muffled or otherwise controlled so as not to exceed 75 db measured at 30 feet from the source of the noise.

- 1. Contact BLM at 575-393-3612 a minimum of 24 hours prior to commencing work. Failure to contact will result in requirement to plug well.
- 2. OPERATOR PROPOSED A SIMILAR RECOMPLETION IN 2007 AND DID NOT COMPLETE THE WORK. AS A RESULT, OPERATOR SHALL HAVE THE WORK PROPOSED COMPLETED AND THE WELL PRODUCING IN PAYING QUANTITIES BY JUNE 20, 2012. OPERATOR SHALL VERIFY PRODUCTION IN PAYING QUANTITIES BY CONDUCTING A 72 HOUR WELL TEST BY A BLM APPROVED INDEPENDENT TESTER.
- 3. On any work over/recompletion, operator shall submit a before and after well bore schematic.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 2,000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

- 9. Replace the CIBP at 4830' with the following: A cement plug is required across the top of the Delaware formation. Operator shall set a Class C plug from 4950' 4790'. Plug shall be a minimum of 25 sacks and tagged at 4790' or shallower.
- 10. Operator shall run a CBL to determine the top of cement on the production casing prior to setting the proposed CIBP at 3350'. BLM to review the CBL prior to placing the CIBP proposed at 3350'.
- 11. If CIBP can be set at 3350', operator shall place a minimum of a 25 sack Class C plug on the CIBP.
- 12. Pressure test to 3000 psi shall be recorded on a chart and held for 30 minutes. Operator stated on a sundry submitted in 2007 that there was a hole in the casing, but did not specify a depth.
- 13. Placement of retainer may be changed based on CBL.
- 14. Pressure test shall be recorded on a chart for 30 minutes.
- 15. Remainder of procedure okay as written.
- 16. Operator shall submit a Subsequent Report Sundry within 30 days of work being completed with all details and dates for recompletion. Current well bore schematic shall be included.
- 17. Operator shall submit a Completion Report for the new completion within 30 days of completion.
- 18. Operator is still responsible for any Incident of Non-Compliance that has been issued.
- 19. Approval for recompletion valid until June 20, 2012.
- 20. Operator to submit work over or plug and abandonment procedure for the GERONIMO FEDERAL 10, WHICH IS ALSO SHUT-IN WITHOUT APPROVAL. Sundry to be submitted by May 15, 2012.

WWI 042012