Submit One Copy To Appropriate District State of New Mexico	72 0 102
Office	Form C-103 Revised November 3, 2011
District I District II Energy, Minerals and Natural Resources Energy, Minerals and Natural Resources	WELL API NO. 30-025-09069
811 S First St., Artesia, NM 88240 DRRS OCH OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1220 South St. Francis Dr.	STATE FEE
District IV 1220 S St. Francis Dr., Santa Fe, NM 1 2012 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOREIGNEDS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	SEVEN RIVERS QUEEN UNIT
1. Type of Well: Oil Well Gas Well Other	8. Well Number 006
2. Name of Operator LINN OPERATING, INC	9. OGRID Number 269234
3. Address of Operator	10. Pool name or Wildcat
600 TRAVIS STREET, SUITE 5100 HOUSTON, TX 77002	EUNICE;SEVEN RIVERS-QUEEN, SOUTH
4. Well Location	
Unit Letter F: 1980 feet from the NORTH line and 1980 feet from the WES	[line /
Section 27 Township 22S Range 36E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc., 3,503'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D	ata
1	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI	-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
OTHER:	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Oper	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been	properly abandoned.
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	concrete. It shows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	ÀRTER/QUARTER LOCATION OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	ÀRTER/QUARTER LOCATION OR Ň HAS BEEN WELDED OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	ÄRTER/QUARTER LOCATION OR N HAS BEEN WELDED OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has	ÄRTER/QUARTER LOCATION OR N HAS BEEN WELDED OR
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment.	ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground If this is a one-well lease or last remaining well on lease, the battery and pit location(s)	ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, productions	ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod from lease and well location.	ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodiftom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.)	ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with uction equipment and junk have been removed
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground lift this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been remote be removed.) All other environmental concerns have been addressed as per OCD rules.	ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground lift this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodiffice the location lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC.	ARTER/QUARTER LOCATION OR N HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground lift this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been remote be removed.) All other environmental concerns have been addressed as per OCD rules.	ARTER/QUARTER LOCATION OR NO HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with auction equipment and junk have been removed aved. (Poured onsite concrete bases do not have all fluids have been removed from non-
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground lift this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodifform lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines.	ARTER/QUARTER LOCATION OR NO HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with auction equipment and junk have been removed aved. (Poured onsite concrete bases do not have all fluids have been removed from non-
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of th	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have All fluids have been removed from non-d lines have been removed well
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground lift this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prodifform lease and well location. All metal bolts and other materials have been removed. Portable bases have been remote to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to sch	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have All fluids have been removed from non-d lines have been removed from lease and well edule an inspection.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of the Operator's pit permit and closure plan. All flow lines, produce the production of the operator of th	been cleared of all junk, trash, flow lines and nd level. have been remediated in compliance with action equipment and junk have been removed wed. (Poured onsite concrete bases do not have All fluids have been removed from non-d lines have been removed from lease and well edule an inspection.
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schematic infrastructure. TITLE: REGULATORY SP	ARTER/QUARTER LOCATION OR NO HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and and level. have been remediated in compliance with auction equipment and junk have been removed aved. (Poured onsite concrete bases do not have all fluids have been removed from non-d lines have been removed from lease and well edule an inspection. ECIALIST III DATE:
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground if this is a one-well lease or last remaining well on lease, the battery and pit location(s) OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to sche SIGNATURE. TITLE: REGULATORY SP	All fluids have been removed from lease and well edule an inspection. ECIALIST III DATE: 5/10/2000

MAY 1 6 2012