

Office

Energy, Minerals and Natural Resources

Revised August 1, 2011

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM

87505

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.
30-025-11751

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
SOUTH JUSTIS UNIT

8. Well Number E-201

9. OGRID Number
24097410. Pool name or Wildcat
JUSTIS-BLINEBRY-TUBB-DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐2. Name of Operator
LEGACY RESERVES OPERATING LP3. Address of Operator
P.O. BOX 10848 MIDLAND, TX 79702

4. Well Location

Unit Letter E : 1980 feet from the North line and 990 feet from the West line
Section 24 Township 25S Range 37E NMPM Lea County11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3076' GL 3087' KB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐OTHER: ☐OTHER: RETURN TO PRODUCTION ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


Mar 13, 2012 - MIRU Lucky WSU, RU tbg testers, PU 4-3/4" CSG swedge & bumper sub, test in hole. Tag @ 5025'. RD tbg testers, POH to 3700'. SDON.Mar 14, 2012 - POH w/tbg & tools, LD csg tools & RIH slick pipe, Tag @ 5025'. POH, SDON.Mar 15, 2012 - PU drill collars, jars, bumper sub & 4-1/4" csg swedge. Tag @ 5025, work through to 5800'. POH w/tbg & tools.Mar 16, 2012 - PU 4-3/4" csg swedge, RIH to 5800'. POH & LD 2-7/8" WS, drill collars and downhole tools. SDFWEMar 19, 2012 - WO weather. PU pump & RIH w/pump & tbg. Set pump @ 5631'. SDON.Mar 20, 2012 - Hook up pump & build wellhead. RDMO.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE SENIOR ENGINEER

DATE 05/07/2012


Type or print name KENT WILLIAMS

E-mail address:

PHONE: 432-689-5200

For State Use Only

APPROVED BY:



TITLE

DATE

Conditions of Approval (if any):

PETROLEUM ENGINEER

MAY 17 2012

MAY 17 2012