(DO NOT USE THIS FORM FOR PROPO	State of New Me Energy, Minerals and Natu HOBBS OCD OIL CONSERVATION MAY 1220 South St. Fram Santa Fe, NM 87 ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLA CATION FOR PERMIT" (FORM C-101) FO Gas Well xx Other	DIVISION ncis Dr. 7505	Form C-103 June 19, 2008  WELL API NO. 30-025-24645  5. Indicate Type of Lease STATE FEE  6. State Oil & Gas Lease No. K-4605  7. Lease Name or Unit Agreement Name North Vacuum Abo North Unit 7-C  8. Well Number 2  9. OGRID Number
Sheridan Production, LLC 3. Address of Operator			10. Pool name or Wildcat North Vacuum
200 N. Loraine Ste. 530 Midland,			Abo
4. Well Location			
	860 feet from the East	_ line and1980	feet from the North line
Section 1	Township 17-S	Range 34-E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4028.9 GR			
12. Check Appropriate Box to Indicate Nature of Notice,  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK XX PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIVED CASING/CEMEN DOWNHOLE COMMINGLE		SEQUENT REPORT OF:  K	
OTHER:		OTHER:	
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>Move in Workover rig. Pull tbg and packer, Scan tbg. Replace tbg, Set packer. Perfs are 8738' – 8851'</li> <li>Spud Date:</li> </ul> Rig Release Date:			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE			