

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
HOBBS Energy Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
RECEIVED  
MAY 17 2012

Form C-103  
June 19, 2008

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-24645
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Sheridan Production, LLC		6. State Oil & Gas Lease No. K-4605
3. Address of Operator 200 N. Loraine Ste. 530 Midland, TX 79701		7. Lease Name or Unit Agreement Name North Vacuum Abo North Unit 7-C
4. Well Location Unit Letter <u>H</u> : <u>860</u> feet from the <u>East</u> line and <u>1980</u> feet from the <u>North</u> line Section <u>1</u> Township <u>17-S</u> Range <u>34-E</u> NMPM Lea County		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4028.9 GR		9. OGRID Number
		10. Pool name or Wildcat North Vacuum Abo

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

**SUBSEQUENT REPORT OF:**  
REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  
4/30/2012 RU Workover rig. Pull tbq and packer, Scan tbq and replace all yellow band. Replace tbq, Set packer and Notify OCD of pressure test. Plan to pressure test on 5/1/2012. Perfs are 8738' - 8851'

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sylvia Shoemaker TITLE Regulatory Analyst DATE 04/27/2012

Type or print name Sylvia Shoemaker E-mail address: sshoemaker@sheridanproduction.com PHONE: 432 596-4266

**For State Use Only**

APPROVED BY: [Signature] TITLE State MGR DATE 5-17-2012  
Conditions of Approval (if any):

MAY 17 2012