Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources		rised August 1, 2011
1625 N French Dr., Hobbs, NM 88240 District II = (575) 748-1283		WELL API NO. 30-025-11853		
District III – (575) 748-1283 811 S First St, Artesia, NM 88240 BBS OCD District III – (505) 334-6178 1220 South St. Francis Dr.		5. Indicate Type of Lease	,	
District III - (505) 334-6178 1220 South St. Francis Dr.		· · · · · · · · · · · · · · · · · · ·	FEE X	
1000 Rio Brazos Rd , Aztec, NM 87410 2 1 2012 District IV - (505) 476-3460 MAY 2 1 2012 Santa Fe, NM 87505		6. State Oil & Gas Lease		
1220 S St Francis Dr , Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit A	greement Name	
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	ON FOR PERMIT" (FORM C-101) FO	OR SUCH		
1. Type of Well: Oil Well XX Gas Well Other		8. Well Number		
2. Name of Operator		9. OGRID Number 141402		
FULFER OIL & CATTLE LLC 3. Address of Operator		10. Pool name or Wildcat		
P.O. BOX 1224, JAL, NM 88252		JALMAT;TAN-YATES-7RVRS(OIL)		
4. Well Location	<u> </u>			
Unit Letter B:	330 feet from the <u>NORTH</u>	H_ line and23	10 feet from the <u>EAS</u>	STline
Section 31	Township 25S	Range 37E	NMPM	County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				april 1984 Paril Disconnection
29 a a a a a a a a a a a a a a a a a a a	92 GR			E. 1
12. Check Appr	opriate Box to Indicate N	ature of Notice,	Report or Other Data	t
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			RING CASING	
TEMPORARILY ABANDON		LLING OPNS.□ P AND	Α 🗆	
PULL OR ALTER CASING		「JOB □		
DOWNHOLE COMMINGLE				
OTHER EXTENSION TO RETURN 1	O PRODUCTION XX	OTHER:		
13. Describe proposed or completed				
of starting any proposed work).		C. For Multiple Con	npletions: Attach wellbore	diagram of
proposed completion or recomp	letion.		•	
REQUEST THREE-MONTH EXTENSI	ON TO RETURN TO PRODU	CTION:	- 3Mo.	
Set RIBP; run MIT test, and clean out ho	le. Put on production.			
				ŕ
<u></u>	 7			
Spud Date:	Rig Release Da	te:		
·				
I hereby certify that the information abov	e is true and complete to the be	est of my knowledge	and belief.	
SIGNATURE Della m	Kelver TITLE 1	AGENT	DATE5	5/21/12
Type or print name DEBBIE MCKE	1 VEV E mail address:	dehmokalyov@cc	rthlink not DUONE: 575	: 202 2575
For State Use Only	E-man address:	_debilickervey@ea	rthlink.net PHONE: <u>575</u>	-342-33/3
		_		
APPROVED BY:	the 5	MEN	GP_DATE S	-22-2012
Conditions of Approval (af any):	_		MAY 2.2	2012
			MAI 2.2	<u> </u>