1	
Submit 1 Copy To Appropriate District OCD Office State of New Mexico Office Financy Minerals and Natural Recourses	/ Form C-103
District I = (575) 393-6161 Energy, Witherars and Natural Resources	Revised August 1, 2011
1625 N French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 MAY <b>2</b> 3 2012	WELL API NO.   30-025-34341
811 S First St, Artesia, NM 88270 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-61 <sup>7</sup> 78 1000 Rio Brazos Rd , Aztec, NM 87410 District IV – (505) 476-3460  RECEIVED  1220 South St. Francis Dr.  Santa Fe, NM 87505	STATE FEE
District IV – (505) 476-3460 <b>RECEIVED</b> Santa Fe, NM 87505 1220 S St Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	W.H. Laughlin
1. Type of Well: Oil Well Gas Well Other	8. Well Number 8
2. Name of Operator / Apache Corporation	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
303 Veterans Airpark Lane, Ste 3000, Midland TX 79705	Monument; Paddock (47080)
4. Well Location F 1760 North 1750 West	
Unit Letter : feet from the line and feet from the line	
Section 9 Township 20-S Range 37-E	NMPM Lea County Lew
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WOR	_
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT	rjob 🗆 🥢
DOWNHOLE COMMINGLE	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
(aa 189' Low 6 5264.  5/9/12 Notify Mark (OCD) of MIRU and BSA intent. RIH w/2 3/8". 5/10/12 RIH tag CIBP @ 5101'	
5/9/12 Notify Mark (OCD) of MIRO and R&A intent. RIH w/2 3/8". 5/10/12 <del>RIH tag</del> CIBP @ 5101' test casing from 5050' to surface 800si 10 min ok. Spot 25x class c and from 5101'-4728'	
5/11/12 Tag Toc @ 4986' Circ well w/ 78 bbls MLF PUH to 4801'. Spot 25x class c cmt.	
Tag toc @ 4418'. Perf @ 3814'. Could not pump into perf pressured up to 1000psi.	
5/14/12 RIH open ended to 3864' Spot 45x class c woc 4hrs. Tag toc 3208'. PUH Perf @ 2498' Sqz 75x class cmt. 5/15/12 RIH tag toc @ 2346'PUH perf @ 1275' Sqz 50x class c displace to 1075'	
5/16/12 RIH tag toc @ 1012' PUH to 90'. Perf @ 170' ND BOP NU wellhead.	Sqz 50x class c
from 170' to surf. Cement circulated out of surf casing. SIP 200psi RD wellhead, anchors and clean location. Install dry hole marker.	oulling unit. Cutoff
Appr	oved for plugging of well bore only.
Liabi	lity under hand is retained pending receipt 103 (Subsequent Report of Well Plugging)
Spud Date: Rig Release Date: white	h may be found at OCD Web Page under
Form	s, www.cmnrd.state.nm.us/pcd.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
r nereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Manager	DATE 5/16/12
SIGNATURE ITILE	DATE
Type or print name E-mail address:	PHONE:
For State Use Only	
APPROVED BY Jones TITLE SAFF ME	9= DATES- 24-2012
	TALE / TO COM