Office District 1 - (575) 393-6161 Energy, Minerals and Natural Resources Revised Augu WELL API NO. 30-025-07917 5. Indicate Type of Lease District II - (505) 334-6178 District IV - (505) 476-3460 District I	et 1 2011
30-025-07917 31 S. First St., Artesia, NM 8820000 CONSERVATION DIVISION 5. Indicate Type of Lease STATE FEE X District IV = (505) 476-3460 MAY 2 9 2012 Santa Fe, NM 87505 6. State Oil & Gas Lease No.	511, 2011
District III - (505) 334-6178 1220 South St. Francis Dr. STATE FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 MAY 2 9 2012 Santa Fe, NM 87505 6. State Oil & Gas Lease No.	
O. State On & Cas Bease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY ND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH DROPOSALS)	. Name
1. Type of Well: Oil Well Gas Well X Other INJECTION 8. Well Number 102	
2. Name of Operator GREAT WESTERN DRILLING COMPANY 9. OGRID Number 009338	
3. Address of Operator P.O. BOX 1659 10. Pool name or Wildcat	
MIDLAND, , TX 79702 SOUTH CARTER SAN ANDRES	
4. Well Location	
Unit Letter N: 330 feet from the SOUTH line and 2310 feet from the WEST	line
Section 5 Township 18S Range 39E NMPM County LEA	641964-0415
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CAS	SING 🗌
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	Ц
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE	
BOWN TOLE SOMMINGLE	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting the state of the s	
I I I I RECEIVE NEORGE OF COMMINION ARCESTABLE IT INVESTIGATE ALL PORTUNANT MAIOUR AND MUCA RECURANT MAIOE INCLUDING AND ACTU	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 05/22/2012	of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 05/22/2012	of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE AREA ENGINEER DATE 05/22/2012 Type or print name SAM ROBERTS E-mail address: sroberts@gwdc.com PHONE: (432)682- For State Use Only	of -5241
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. RE-SET THE PACKER AND PRESSURE TEST TUBING X CASING ANNULUS TO 300 PSI. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE AREA ENGINEER DATE 05/22/2012 Type or print name SAM ROBERTS E-mail address: sroberts@gwdc.com PHONE: (432)682-	of -5241