		New Me				Form C			
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals	March 4, 2004 WELL API NO.							
District II 1301 W. Grand Ave., Artesia, NM 88210	0 OIL CONSERVATION DIVISION				30-025-36815				
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE X					
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505				oil & Gas Lease				
1220 S. St. Francis Dr., Santa Fe, NM 87505									
SUNDRY NOTICES AND REPORTS ON WELLS					Name or Unit A	greement Na	ime		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					urner Jr B				
PROPOSALS.)					8. Well Number				
1. Type of Well: Oil Well X Gas Well Other					008				
) Number				
2. Name of Operator Amerada Hess Corporation					5				
3. Address of Operator P.O. Box 840					name or Wildca				
	TX 79360				/est Nadine Tub		est		
4. Well Location				Nadine Pa	ddock Blinebry	(47400)			
Unit Letter O :	390 feet from the	South	line and	1980	feet from the	East	_line		
Section 17	Township			NMPM	Count	ty Lea	na fi a tamang - aria a		
	11. Elevation (Show wi	hether DR,	RKB, RT, GR, etc	.)					
Pit or Below-grade Tank Application (For	jit or below-grade tank close	ures, a form	C-144 must be attach	ed)					
Pit Location: ULSectTwp					e from nearest fre	sh water well_			
Distance from nearest surface water	Below-grade Tank Loc	cation UL	SectTw	pRng_	;				
feet from theline and	feet from the	line							
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK	PLUG AND ABANDON			BSEQUEN	IT REPORT	OF:			
	CHANGE PLANS		COMMENCE DF			RING CASINO AND	3 🗆		
PULL OR ALTER CASING	MULTIPLE		COMMENCE DF	RILLING OPN			3 🗆		
PULL OR ALTER CASING		_	COMMENCE DF CASING TEST A CEMENT JOB	RILLING OPN	IS. PLUG ABANI	AND DONMENT			
PULL OR ALTER CASING	MULTIPLE COMPLETION		COMMENCE DR CASING TEST A CEMENT JOB OTHER: Downho	RILLING OPN AND ole comming!	e Blinebry/Tubb	AND DONMENT /Drinkard			
PULL OR ALTER CASING	MULTIPLE COMPLETION leted operations. (Clearly		COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an	RILLING OPN AND ple comming! nd give pertii	e Blinebry/Tubb	AND DONMENT //Drinkard ding estimat			
PULL OR ALTER CASING	MULTIPLE COMPLETION leted operations. (Clearly rk). SEE RULE 1103. F	y state all p	COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an	RILLING OPN AND ple comming! nd give pertii	e Blinebry/Tubb	AND DONMENT //Drinkard ding estimat			
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl of starting any proposed wo or recompletion.	MULTIPLE COMPLETION eted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01	y state all p For Multipl	COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an	RILLING OPN AND ple comming! nd give pertii	e Blinebry/Tubb	AND DONMENT //Drinkard ding estimat			
PULL OR ALTER CASING	MULTIPLE COMPLETION eted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01	y state all p For Multipl	COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an	RILLING OPN AND ple comming! nd give pertii	e Blinebry/Tubb	AND DONMENT //Drinkard ding estimat			
PULL OR ALTER CASING	MULTIPLE COMPLETION leted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01 D, 114 MCFPD, 220 BWF	y state all p For Multipl 1024 B	COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an le Completions: A	RILLING OPN AND ole comming! nd give pertii Attach wellbo	e Blinebry/Tubb e Blinebry/Tubb nent dates, inclu re diagram of p	AND DONMENT //Drinkard iding estimat roposed com	Ed date pletion		
PULL OR ALTER CASING	MULTIPLE COMPLETION eted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01 D, 114 MCFPD, 220 BWF above is true and comple closed according to NMOCD	y state all p For Multipl 102 & B PD	COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an le Completions: A	RILLING OPN AND ole comming! nd give pertii Attach wellbo ge and belief] or an (attach	e Blinebry/Tubb e Blinebry/Tubb nent dates, inclure diagram of p	AND DONMENT //Drinkard iding estimat roposed com	Ed date pletion		
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl of starting any proposed wo or recompletion. Please refer to Order R-11363 & Well test on 2/1/2005: 143 BOPE See attached I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE	MULTIPLE COMPLETION eted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01 D, 114 MCFPD, 220 BWF above is true and comple closed according to NMOCD	y state all p For Multipl 1024 B PD te to the be guidelines [COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an le Completions: A set of my knowled , a general permit [Senior Advisor/Reg	RILLING OPN AND ole comming! nd give pertin trach wellbo ge and belief or an (attach gulatory	E Blinebry/Tubb e Blinebry/Tubb nent dates, inclured diagram of p	AND DONMENT //Drinkard ding estimat roposed-com	Ed date pletion		
PULL OR ALTER CASING	MULTIPLE COMPLETION eted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01 D, 114 MCFPD, 220 BWF above is true and comple closed according to NMOCD	y state all p For Multipl 1024 B PD te to the be guidelines [COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an le Completions: A set of my knowled , a general permit [Senior Advisor/Reg	RILLING OPN AND ole comming! nd give pertin trach wellbo ge and belief or an (attach gulatory	E Blinebry/Tubb e Blinebry/Tubb nent dates, inclured diagram of p	AND DONMENT //Drinkard ding estimat roposed com	Ed date pletion		
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl of starting any proposed wo or recompletion. Please refer to Order R-11363 & Well test on 2/1/2005: 143 BOPE See attached I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE	MULTIPLE COMPLETION eted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01 D, 114 MCFPD, 220 BWF above is true and comple closed according to NMOCD	y state all p For Multipl 1024 B PD te to the be guidelines [COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an le Completions: A est of my knowled , a general permit [Senior Advisor/Reg	RILLING OPN AND ole comming! nd give pertin trach wellbo ge and belief or an (attach gulatory	E Blinebry/Tubb e Blinebry/Tubb nent dates, inclured diagram of p	AND DONMENT //Drinkard ding estimat roposed com	Ed date pletion		
PULL OR ALTER CASING	MULTIPLE COMPLETION eted operations. (Clearly rk). SEE RULE 1103. F DHC Order No. HOB-01 D, 114 MCFPD, 220 BWF above is true and comple closed according to NMOCD	y state all p For Multipl 1024 B PD te to the be guidelines [COMMENCE DF CASING TEST A CEMENT JOB OTHER: Downho pertinent details, an le Completions: A set of my knowled , a general permit [Senior Advisor/Reg	RILLING OPN AND ole comming! nd give pertin trach wellbo ge and belief or an (attach gulatory	E Blinebry/Tubb e Blinebry/Tubb nent dates, inclured diagram of p	AND DONMENT //Drinkard ding estimat roposed com	below- an .		

¥

40

Form C-103 Attachment

Amerada Hess Corporation OGRID 000495 Fred Turner B Jr. No. 8 API 30-025-36815 Refer to Order No. R-11363 & DHC Order No. HOB-0102A

9/29/2004 thru 1/20/2005

9/29-9/30: Key Energy Svc MIRU pulling unit. TIH w/4 $\frac{3}{4}$ " bit & tbg. Tagged in 5 $\frac{1}{2}$ " csg @ 6826'. Established circulation & drilled cement from 6826' to 7134'. Circ clean & press csg w/1000 psi for 30 min. Held OK. CI 10/1-10/2.

10/3-10/4: Baker Wireline MIRU and ran CBL from 7130'-3000'. RD Baker Wireline. Drilled out cement from 7134'-7608' & circulate clean. TIH w/5 1/2" pkr set @ 7103'.

10/5-10/6: RU BJ Svc. Pumped 6800 gals of 15% Skaggs Blend Acid. RD BJ Svc. Swabbed well. Released pkr & tbg. CI 10/7-10/10.

10/11: Baker Wireline Svc MIRU, TIH and set CIBP @ 7105'. Loaded csg and press CIBP w/1000 psi. Held OK. Baker Wireline perf'd 5 ½" csg in Drinkard zone using 3 1/8" guns @ 3 spf in following intervals: 6860'-6862.5', 6889'-6891.5', 6930'-6935.2', 6956'-6960' & 6987'-6992.5'. RD Baker.

10/12-10/13: BJ Svc MIRU, press tested lines w/6000 psi, tested tbg & pkr w/5000 psi. Acidized Drinkard zone perfs from 6882'-6992' w/2900 gals 15% HCL Skaggs Blend Acid. Swabbed well. Cl 10/14-10/18.

10/19-10/20: Treated Drinkard perfs from 6860'-6992' w/140,000 gals Spectra Star Frac 30# XL Borate & 272,000# of 20/40 sand. Swabbed well. CI 10/21-10/23.

10/24: Baker Atlas Wireline Svc MIRU & perf'd 5 ½" csg in Tubb & upper Drinkard zones w/4" guns @ 3 spf in following intervals: 6515'-6517.6', 6559'-6562.6', 6636'-6638.3', 6659'-6662.9', 6729'-6733.1', & 6779'-6781.1'. RD Baker Atlas.

10/25-10/26: BJ Svc MIRU & acidized Tubb & Upper Drinkard zone perfs w/ 4500 gals of 15% HCL Skaggs Blend Acid. Swabbed well. CI 10/27-11/3.

11/4: Halliburton Svc MIRU pumping eqpt. Set retainer @ 6452'. Loaded tbg & press w/2500 psi. Loaded csg, established circulation & spotted cement to within 4 bbls of cement retainer. Cement squeezed Tubb & Drinkard zone perfs from 6515'-6781'. Pumped total of 150 sx and 100 sx of premium plus cement w/ 4/10% HALAD 322 & 50 sx of premium plus neat cement. Pulled out of cement retainer, circulated clean. Cl 11/5-11/6.

11/7-11/8: TIH w/4 ³/₄" bit. Tagged cement retainer @ 6448'. Drilled out retainer from 6448'-6454'. Tagged TOC @ 6550'. Circulated clean. Drilled out cement from 6550'-6796'. Tagged CIBP @ 6861'. Circ. clean. Press csg w/500 psi. TOH w/tbg & bit.

11/9: RU Schlumberger Well Svc. Set CIBP @ 6720'. Perf Blinebry/Tubb w/4" csg guns @ 3 spf Blinebry f/6328'-6331.5', Tubb f/6515'-6517.9', 6559'-6563', 6636'-6639.2', 6659'-6664.4'.

RD Schlumberger. TIH w/5 1/2" pkr and tbg @ 6697'. Test CIBP to 1000 psi. Held OK. Released pkr.

11/10: RU BJ Svc, set pkr @ 6678' & test to 2500 psi. Acidize w/4500 gals of 15% acid. Swabbed well. CI 11/11-11/16

11/17: Test lines to 7000#. Treat Lower Blinebry/Tubb perfs f/6328'-6664' w/115,000 gals of Spectra Star Frac 30# XL Borate & 250,000# of 20/40 sand. RD BJ Svc.

11/18-11/21: Key Energy Svc MIRU pulling unit & cleaned out frac sand from 6637'- top of CIBP @ 6720'. Circ clean. Set pkr @ 6258'. Remove BOP, installed wellhead. Swabbed well. CI 11/22-11/29.

11/30-12/5: Hook up prod equipment and open well to production facility.

12/13: MIRU Key Energy & TOH w/tbg. CI

12/14: MIRU Baker Atlas & TIH w/CIBP set @ 6300'. Test lines to 1000#. TIH w/3.125 csg guns & perf'd Blinebry zone @ following intervals: 5893'-5897.5', 5946'-5950.6', 5988'-5990.4', 6041'-6044.7', & 6088'-6091.8'. CI well.

12/16: MIRU BJ Svc & acidized Blinebry perfs from 5893'-6091.8' w/4500 gals 15% HCL acid. RDMO BJ Svc. Swab well. CI well.

12/20: ND BOP & install frac valve. CI well.

12/22: RU BJ Svc & test lines to 6000#. Treat Blinebry perfs from 5893'-6092' w/95,500 gals spectrastar 30# XL Borate & 252,500# of 16/30 sand. CI well.

12/28: RU Key Energy & TIH w/tbg. Tagged fill @ 6148'. Cleaned out frac sand down to 6300' @ top of CIBP.. Drilled and pushed plug down to 6461'. CI well.

1/3/2005: TIH w/bit & tbg & tagged sand @ 6466'. Cleaned out fill to 6720' to top of CIBP. Drilled on plug down 10' and CI well.

1/5: TIH w/bit & drilled & pushed plug down to 6830'. Drilled cement down to 6850'. CI well.

1/6: TIH w/bit & tagged cement @ 6892'. Drilled cement from 6892' to 6986'. Moved bit down hole to 7105' top of CIBP. CI well.

1/10: TIH w/51/2" pkr set @ 6813'. RU swab eqpt & swab well. CI well.

1/11: MIRU Schlumberger & reperf Drinkard zone in following intervals: 6855'-6865', 6889'-6891', 6930'-6935.2', 6956'-6960', 6987'-6992.2'. CI well.

1/12: Swab well. MIRU BJ Svc & acidize Drinkard perfs from 6855'-6992.5' w/4000 gals 15% HCL Skaggs blend acid. Swab well. No oil or gas recovered. CI well.

1/17: TIH w/tbg, ND BOP, NU wellhead. CI well.

1/18: TIH w/new 25-175-RHBC-20-6-S-4 sucker rod pump #A-1008. Cleaned location & RDMO pulling unit. CI well.

1/19: Install pumping unit. CI waiting on electricity.

J.

.

1/20: Begin producing well from West Nadine Paddock Blinebry (47400), West Nadine Tubb (47530) & Skaggs Drinkard (57000) zones.

Test on 2/1/2005 of 143 BOPD, 114 MCFD, 220 BWPD.

	OIL		GAS		WATER	
WEST NADINE PADDOCK BLINEBRY (47400)	41	29%	31	27%	64	29%
WEST NADINE TUBB (47530)	49	34%	11	10%	75	34%
SKAGGS DRINKARD (57000)	53	37%	72	63%	81	37%
TOTAL	143	100%	114	100%	220	100%