

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

Injection - Single Zone

2. Name of Operator

APACHE CORPORATION

3a. Address

6120 S. YALE, STE. 1500 TULSA, OK 74136

3b. Phone No. (include area code)

918-491-4980

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC 6-22S-37E

330 FSL & 330 FEL

5. Lease Serial No. **LC-032573(b)**
30-025-37042

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

ELLIOTT B No. ✓

9. API Well No.

10. Field and Pool, or Exploratory Area

SWD; SAN ANDRES

11. County or Parish, State

LEA

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|---|---|---|--|--|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input checked="" type="checkbox"/> Other <u>SPUD, SURF. CSG.,</u> |
| | <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | <u>LOG, PROD. CSG.</u> |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

2/5/05 SPUD 12 1/4" HOLE - DRILL & SURVEY FROM 40'-997.

2/6/05- DRILL & SURVEY FROM 997-4406. CIRCULATE TO RUN CSG. DROP TOTCO - POH W/ BIT. RIH 25 JTS. 1163.77' 9 5/8" 40# J55 LT&C CSG. 2/15/05 W/ 9 CENTRALIZERS. BJ CMT. SHOE @ 1160 - FC @ 1110 W/ 350 SX 35:65 POZ W/ 6% GEL + 2% CACL + 1/4# CF = 117 BBLS. 12.7# SLURRY W/ 1.88 YIELD & 175 SX CLASS C W/ 2% CACL + 1/8# CF = 42 BBLS. 14.8# SLURRY W/ 1.35 YIELD - PLUG BUMPED & HELD - CIRC 119 SX. CMT. TO PIT WOC CUT OFF CSG. - WELD ON HEAD NU BOP & CHOKE MANIFOLD TEST CHOKE MANIFOLD - CSG. - BLIND RAMS- PIPE RAMS- ANNULAR 1500# RIH W/ BIT # 2 RIH W/ BIT # 2 DRILL CMT. & EQUIP. DRILL 3664-4134 SURVEY @ 4103= 1.0 DRILL 4134-4386 ; RAN FLD. CALIPER @ 4300 DRILL 4386-4406 CIRCULATE FOR CSG. SURVEY @ 4383 = 1.0 POH W/ BIT RACK CASING - RIG UP CASING HAND RIH 103 JTS. 4412.4' 7" 26# J55 LT&C CSG. W/ 12 CENTRALIZERS BJ CMT. SHOE @ 4406 - FC @ 4360 W/ 600 SX 35:65 POZ W/ 6% GEL + 5# SALT/SX = 206 BBLS. 12.7# SLURRY W/ 1.93 YIELD & 150 SX VCLASS C + 3% KCL = 36 BBLS. 14.8# SLURRY W/ 1.34 YIELD - PLUG BUMPED & HELD - CIRC 107 SX. CMT. TO PIT ND BOP - SET SLIPS - CUT OFF CSG. - NU BOP EQUIP- CHANGE RAMS TO 3 1/2" - TEST BOP EQUIP. - ANNULAR LEAKING REPLACE ANNULAR TEST ANNULAR - NO TEST - BLM O'KAYED DRILLING WITHOUT IT- TEST ACCUMULATOR- NO TEST .WAIT ON ELECTRICIAN - REPAIR ACCUMULATOR TEST BLIND RAMS & BOP EQUIP. 1500# RIH W/ BIT # 3 DRILL CMT. & EQUIP. DRILL 4867-4893. SURVEY @ 4861= 0.75 DRILL 4893-5050. CIRCULATE SURVEY @ 4988= 0.5. POH W/ BIT ND BOP - INSTALL "B" SECTION HEAD- INSTALL BOP - CLOSE BLIND RAMS- RELEASE

RIG @ 3:00 AM 2-15-2005

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

LANA WILLIAMS

Title DRILLING CLERK II

Signature

Lana Williams

Date 4/11/2005

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

DAVID E. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)