Submit 1 Copy To Appropriate District State of New	Mexico	Form C-103		
Office Energy, Minerals and N		Revised August 1, 2011		
1625 N. French Dr , Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St. Artesia NM 88210		WELL API NO. 30-025-00518		
District III – (505) 334-6178		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 JUN <b>0 4</b> 2072 Santa Fe, NM		STATE     FEE       6. State Oil & Gas Lease No.		
1220 S St. Francis Dr , Santa Fe, NM 87505		B2229		
SUNDRY NOTICHE PORTS ON WEI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR		7. Lease Name or Unit Agreement Name Malmar Unit		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 PROPOSALS.)				
1. Type of Well: Oil Well 🔲 Gas Well 🗌 Other WIW		8. Well Number 310		
2. Name of Operator VPR OPERATING, LLC		9. OGRID Number 266091		
3. Address of Operator		10. Pool name or Wildcat		
1406 CAMP CRAFT ROAD, SUITE 106, AUSTIN, TX 787464. Well Location	· · · · · · · · · · · · · · · · · · ·	Maljamar; Grayburg-San-Andres		
Unit Letter_J :1980feet from theSouth	line and1980	feet from the East line		
Section 12 Township 175	v	NMPM Lea County		
11. Elevation (Show whether	DR, RKB, RT, GR, etc.,			
12. Check Appropriate Box to Indicate	e Nature of Notice,	Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK  PLUG AND ABANDON  FEMPORARILY ABANDON  CHANGE PLANS		REMEDIAL WORK     ALTERING CASING       COMMENCE DRILLING OPNS.     P AND A		
PULL OR ALTER CASING	CASING/CEMEN			
		_		
OTHER: 13. Describe proposed or completed operations. (Clearly state a	OTHER:	d give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NM				
proposed completion or recompletion.				
8 5/8" 24# csg set at 305' x Cmt w/ 250 sx 50/50 Poz w/ 2% CaCl 5 ½"14# csg set at 4520' x Cmt w/300sx 50/50 Poz x TOC calcula		to surface		
San Andres Perforations 4217-4453' x Cast iron bridge plug set a				
VPR proposes to plug and abandon as follows				
Run open ended tubing x tag CIBP at 4160' x Spot 25sx cement plug x WOC and tag plug Displace well with gelled brine				
Perforate 2550' x Squeeze w/ 35sx cmt x WOC and tag plug at or				
Perforate 1470' x Squeeze w/ 35sx cmt x WOC and tag plug at or Perforate 355' x Establish circulate 8 5/8" x 5 ½"annulus x Circu				
Leave well full of cement x Cut off well head and install PA mark				
Clean and level location for inspection and release Enclosures; Before and after well diagrams, C144 CLEZ				
- The Oil	Conservation Division	- An Must be notified		
		ing of plugging operations.		
I haraby partify that the information above is two and second to the the		11 1/ 0		
I hereby certify that the information above is true and complete to the $\sqrt{200}$	e best of my knowledg	e and belief.		
SIGNATURE ////////////////////////////////////		DATE_05/31/12		
Type or print name Ropert B. Pullen, Sr. E-mail add For State Use Only	ress: BOQ VProf	R(a) 19 Con RHONE: 512-327-8776		
APPROVED BY: Approval (if ang):	mpliance	ficer DATE 6/6/2012		
Conditions of Approval (II ally).	•	() chm		

APPROVED BY:	$\mathbf{u}$	ler	X
APPROVED BY: Conditions of App	roval	(if an	<b>s</b> ):

∹. ..

JUN 0 7 2012



BEP

.



BEP

.

.