Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.
1625 N French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		30-025-01849	
BILS First St., Artesia, NACE PRINCE OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
1000 Rio Brazos Rd , Aztec, NM 87410		STATE S FEE	
District IV – (505) 476-3460 1220 S St Francis Dr , Santa Fe, NM 8/505 87505		6. State Oil & Gas Lease No. E-2793	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR LOCATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			West Ranger Unit
1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD			8. Well Number 6
2. Name of Operator EverQuest Energy Corporation			9. OGRID Number 212929
3. Address of Operator			10. Pool name or Wildcat
10 Desta Drive, Suite 300-East, Midland, Texas 79705			SWD; tenn -
4. Well Location			
Unit Letter N:1978 feet from the West line and 660 feet from the South line			
Section 23 Township 12S Range 34E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Elevation (Snow whether DK, KKD, KT, OK, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	UG AND ABANDON	REMEDIAL WORK	
	IANGE PLANS	COMMENCE DRIL	-
PULL OR ALTER CASING MIDOWNHOLE COMMINGLE	JLTIPLE COMPL	CASING/ÇEMENT	JOB T
DOWN TOLE COMMINITABLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
This SWD takes water on a vacuum. In advance of scheduled MIT test found annulus on a			
vacuum. Attempted to load casing with 50 bbls of produced water – would not fill. Shut down			
injection and all production in the field pending workover. Locate WSU and move-in over the			
weekend. Prepared to pull tubing and packer to locate problem. Called Sylvia Dickey with OCD-			
Hobbs to alert her of the situation and to defer the scheduled MIT test of 5-30-12 until the			
workover is completed.			
1			
Spud Date: 5-29-12	Rig Release	Date:	
•	•		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
increby certify that the information above is true and complete to the best of my knowledge and benefit.			
SIGNATURE MC Oufl	us s	TITLE: Presider	nt DATE: 5-30-12
	/		
Type or print name: Terry Duffey For State Use Only	E-mail address:		PHONE: 432-686-9790
APPROVED BY: Walkin	Lalen TITLE Com	الم يبدنام	Cer DATE 06-06-12
APPROVED BY:Conditions of Approval (if any):	TITLE COM	Jon ance O'M	DATE OB-OG-12

JUN 0 7 2012

 $O_{n_{\nu}}$