

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBS OGD CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 15 2012

WELL API NO. 30-025-01340
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: STATE BY
8. Well Number #003
9. OGRID Number 005380
10. Pool name or Wildcat <u>Corbin, On</u> VACUUM - GRAYBURG - SAN ANDRES
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4035' - GR

SUNDRY RECEIVED AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐
2. Name of Operator XTO ENERGY, INC.
3. Address of Operator 200 N. LORAIN, SUITE 800, MIDLAND, TEXAS
4. Well Location Unit Letter <u>I</u> : <u>1980</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>EAST</u> line Section <u>32</u> Township <u>17S</u> Range <u>33E</u> NMPM County <u>LEA</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4035' - GR

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC.. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) TAG EXISTING 7" CIBP @ +/-3,770'; PRES. TEST 7" CSG. TO 500#; PUMP A 35 SX. CMT. PLUG @ 3,770'-3,640'.
- 2) CIRC. WELL W/ P/A FLUID.
- 3) PERF. X ATTEMPT TO SQZ. A 45 SX. CMT. PLUG @ 2,670'-2,550' (B/SALT); WOC X TAG TOP OF CMT. PLUG.
- 4) PERF. X ATTEMPT TO SQZ. A 40 SX. CMT. PLUG @ 1,690'-1,580' (T/SALT); WOC X TAG TOP OF CMT. PLUG.
- 5) PERF. X ATTEMPT TO SQZ. A 45 SX. CMT. PLUG @ 1,420'-1,290' (8-5/8" CSG. SHOE X T/ANHY.); WOC X TAG PLUG.
- 6) PERF. X CIRC. TO SURF. A 75 SX. CMT. PLUG @ 150'-3' MAKING SURE ALL ANNULI ARE FILLED.
- 7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARKER.

Spud Date:

Rig Release

The Oil Conservation Division Must be notified
24 hours prior to the beginning of plugging operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David A. Eyer TITLE AGENT DATE 06/12/12
deyler@milagro-res.com
Type or print name DAVID A. EYER E-mail address: deyler@milagro-res.com PHONE 432.687.3033

For State Use Only
APPROVED BY Maley Brown TITLE Compliance Officer DATE 6/18/2012
Conditions of Approval (if any):

JUN 18 2012

30-025-01340

STATE BY #003

GL: 4035'

10-1/4" HOLE

TOC ~ 940' (CALC.)

8-5/8" 24# K-55 @ 1370'. CMT W/50SX.

8" HOLE

TOC ~ 3,165' (CALC.)

CIBP @ 3770'

7" 20# K-55 CSG @ 3813'. CMT'D W/100SX.

SHOT 3916'-3936' W/180 QTS NITRO.

PBTD @ 3936'.
TD @ 4715'.

10SX CMT, 10' GRAVEL, 3SX CMT PLUG @ 4715'-
3936'.

DAE 06/12/12

30-025-01340

STATE BY #003

GL: 4035'

10-1/4" HOLE

PXA
FLUID

TOC ~ 940' (CALC)

8-5/8" 24# K-55 @ 1370'. CMT W/50SX.

PXA
FLUID

PXA
FLUID

8" HOLE

PXA
FLUID

TOC ~ 3,165' (CALC.)

CIBP @ 3770'

7" 20# K-55 CSG @ 3813'. CMT'D W/100SX.

SHOT 3916'-3936' W/180 QTS NITRO.

PBTD @ 3936'.
TD @ 4715'.

10SX CMT, 10' GRAVEL, 3SX CMT PLUG @ 4715'-
3936'.

DAE 06/12/12