Submit 1 Copy To Appropriate District Office State of New Me	
District I Energy, Minerals and Natural Resources October 13, 2009	
1625 N French Dr., Hobbs, NM 8824 HOBBS OCD	WELL API NO. 30-025-33428
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	DIVISION 5. Indicate Type of Lease
1000 D. Droppes D.d. Anton NIM 97NIMIY & Z. ////	SIAIE N FEE I
District IV Santa Fe, NM 87	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr , Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS)	OR SUCH CENTRAL VACUUM UNIT
1. Type of Well: Oil Well Gas Well Other	8. Well Number 202
2. Name of Operator	9. OGRID Number 4323
CHEVRON U.S.A. INC.	
3. Address of Operator	10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS 79705	VACUUM GRAYBURG SAN ANDRES
4. Well Location	
Unit Letter H: 1870 feet from the NORTH line and 890 feet from the EAST line	
Section 6 Township 18S Range 35E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
•	
12. Check Appropriate Box to Indicate N	ature of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
DOWNHOLE COMMINGLE	
OTHER:	OTHER: RECOMPLETION & WELL NAME CHANGE
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
proposed completion of recompletion.	
2-15-12: MIRU. 2-16-12: TIH & TAG @ 5915. DUMP 35' CMT ON CIBP. PERFORATE 4999-5075. 2-17-12: SET PKR @ 4945.	
PMP 10,000 GALS 15% ACID. 2-18-12: RESET PKR @ 4955. SWABBING. 2-22-12: SET RBP @ 5047. 2-24-12: LATCH	
ONTO RBP. RELEASED. SET PKR @ 4690. PERFS @ 4999-5075. 2-25-12: SET RBP @ 5433. PKR @ 5391. CIRC W/130 BFW.	
DROP 20' SAND ON TOP OF RBP. TIH W/CMT RET TO 4114. HANGING. 2-27-12: SET RET @ 4850. 2-28-12: CMT W/150	
SX CMT CL C NEAT, & 50 SX CL C NEAT W/2%CACL. STUNG OUT OF CMT. REV OUT W/7 BBLS CMT IN TBG.	
2-29-12: TAG CMT @ 4842. DRILL 8' CMT TO RET. TAG RET @ 4850. 3-01-12: DRILL CMT TO 5048. 3-02-12: DRILL	
WELL TO 5048. ADDED 23' FOR GUNS & CCL TO REACH 5025. 3-03-12: TAG @ 5050. DRILL 30' CMT FR 5050-5080. TAG	
SAND @ 5427. 3-06-12: RAN CPNL LOG FR 5420-3300. PERF 5 ½" CSG FR 5010-5023, 5034-5042, & 5050-5054. SET RBP @ 5058. (5' ABOVE SQZD SET OF PERFS @ 5063 & 8' BELOW COLLAR). 3-07-12: PKR NOT HOLDING. 3-08-12: TIH W/SAND	
LINE & FISH SPOT CONTROL VALVE. 3-09-12: TIH TO 4500. TAG RBP @ 5058. PU TO 5057. SPOT 31 BBLS 15% HCL DN	
TBG. ACIDIZE BTM PERFS 5050-5054 W/4 BBLS ACID. ACIDIZE TOP PERFS 5010-5025 W/1 BBL ACID. REV CIRC. PMP 90	
BW DN BACKSIDE. 3-10-12: SET PKR @ 4946. ACIDIZE PERFS 5010-5023, 5034-5042, 5050-5054 W/50 BBLS 15% HCL.	
SWAB. 3-13-12: REL PKR. REL PLUG.WASH 20' SAND OFF. PULL ABOVE PERFS. 3-14-12: PU BHA & 2 7/8" TBG.	
3-15-12: BOT @ 5184. TAC @ 4932. TIH W/PUMP & RODS. 3-16-1	2: RIG DOWN. W/O TEST.
05-30-12: ON 24 HR OPT. PUMPING 6 OIL, 5 GAS, 36 WATER. G	OP 710
05-50-12. ON 24 TIK OF 1. TOWN ING O OIL, 5 GAS, 50 WATER. G	OR-/19
Formerly VACUUM GLORIETA WEST UNIT #132	
I hereby certify that the information above is true and complete to the be	est of my knowledge and belief.
\bigcirc . \bigcirc .	
- X - A - A - A - A - A - A - A - A - A	PA Vacuum Glorieda
SIGNATURE TITLE REG	ULATORY SPECIALIST DATE 06-21-2012
Type or print name DENISE PINKERTON E-mail address: leak	raid@ahauran aam DHONE: 422 CRZ ZZZZ
Type or print name DENISE PINKERTON E-mail address: <u>leak</u> For State Use Only	rejd@chevron.com PHONE: 432-687-7375
	TOMPEHM ENGINEERO IIIN A P.
APPROVED BY: TITLE	TROLEUM ENGINEER DATE JUN 25 2012
	JUN 2.5 2012