

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

| |
|---|
| WELL API NO. 30-025-07766 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name Blankenship "BCD" |
| 8. Well Number 1 |
| 9. OGRID Number 873 |
| 10. Pool name or Wildcat House; San Andres |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Apache Corporation

3. Address of Operator
303 Veterans Airpark Lane, Ste 3000, Midland TX 79705

4. Well Location
Unit Letter E : 1980 feet from the North line and 660 feet from the West line
Section 12 Township 20-S Range 38-E NMPM Lea County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3557 GR

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of
C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.emnrd.state.nm.us/oed
TELEPHONE
PULL OR
DOWNHOLE COMPLETION

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTIFICATION TO:

ABANDON ☐

☐

☐

☐

☐

☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

P AND A ☒

CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed work (early state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE 15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/8/12 Notify Mark (OCD) of P&A intent. 6/11/12 MIRU RIH Tag CIBP @ 6600'. Circ MLF to 4200'. Spot 25x class c. PUH to 5690'.
6/12/12 Spot 25x @ 5690'. POH pick up 5 1/2" pkr RIH to 4020' RUWL Perf @ 4332'. Sqz 50x class "c".
6/13/12 RIH Tag Toc @ 4093'. PUH to 3960'. Circ well w/ 94 lbs MLF. PUH perf @ 3960'. Sqz 50x class "c".
6/14/12 RIH Tag Toc @ 3536'. PUH perf @ 3200'. Sqz 140x class "c". woc 4 hrs. RIH Tag Toc @ 2627'. PUH perf @ 1660'. Sqz 50x class "c".
6/15/12 RIH Tag Toc @ 1444'. PUH perf @ 357'. Sqz 110x class "c". Circ from 357' to surf. Cutoff wellhead, anchors, clean location. Install dryhole marker, rig down pulling and all P&A Equip.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jimmy Bagley

TITLE

Manager

DATE

6/15/12

Type or print name

Jimmy Bagley

E-mail address:

PHONE:

432-561-8600

For State Use Only

APPROVED BY

E. E. Bagley

TITLE

State Manager

DATE

6-26-2012

Conditions of Approval (if any):

JUN 26 2012