

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N French Dr, Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St, Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd, Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr, Santa Fe, NM 87505

HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

JUL 03 2012

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

RECEIVED

|   |
|---|
| WELL API NO.<br>30-025-09198 ✓  |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name<br>Emery King "SE" ✓   |
| 8. Well Number 5 ✓  |
| 9. OGRID Number<br>143199 ✓   |
| 10. Pool name or Wildcat<br>Langlie Mattix (7R-Q) ✓   |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.)  |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator  
EnerVest Operating, LLC

3. Address of Operator  
1001 Fannin Street, Suite 800 Houston, TX 77002

4. Well Location  
Unit Letter P : 990 feet from the South line and 990 feet from the East line  
Section 1 Township 23S Range 36E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Temporary Abandonment ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-27-12: MIRU well testers.  
Set CIBP @ 3505' GL.  
Dump 40' cmt on top. Top perf = 3620'.  
Sylvia Dickey w/Hobbs OCD was present for test.  
Pressured to 560 # for 30 mins - OK. Please see attached chart.

HOBBS OCD

JUL 03 2012

RECEIVED

This Approval of Temporary  
Abandonment Expires 9/27/2012

Spud Date:

10-19-59

Rig Release Date:

10-31-59

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Pamela Fry TITLE Assoc. Regulatory Analyst DATE 6-29-12

Type or print name Pamela Fry E-mail address: pfry@enervest.net PHONE: 713-495-1563

For State Use Only

APPROVED BY: Maley Brown TITLE Compliance Officer DATE 7/5/2012

