Submit I Copy To Appropriate District Office	State of New Mo	exico	Form C-103
District I – (575) 393-6161 Er	nergy, Minerals and Natu	ıral Resources	Revised August 1, 2011
1625 N. French Dr , Hobbs, NM 88240		WELL API NO.	
District II – (\$75) 748-1283 811 S First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-35533
<u>District III</u> – (505) 334-6178	1220 South St. Fran	ncis Dr.	5. Indicate Type of Lease STATE FEE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S St. Francis Dr , Santa Fe, NM	,		o. State on & das Lease 110.
87505			
SUNDRY NOTICES AN (DO NOT USE THIS FORM FOR PROPOSALS TO	ID REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION F	OR PERMIT" (FORM C-101) F	OR SUCH	Townsend State Com
PROPOSALS.)			8. Well Number
1. Type of Well: Oil Well Gas We	ll 🛛 Other 🖊 🔣	0 5 2012	10
2. Name of Operator			9. OGRID Number
Devon Energy Production Co, LP		CEN/ED-	6137
3. Address of Operator		ASIABI	10. Pool name or Wildcat
333 West Sheridan Avenue, Oklahoma City	, OK 73102-8260		Shoe Bar North Atoka
4. Well Location			
Unit Letter C: 800 feet from the North line and 1980 feet from the West line			
Section 3 Township 16S Range 35E NMPM County Lea			
	evation (Show whether DR		
The state of the s	KB; 4014 GL	, , , ,	
12 Check Appropri	riate Box to Indicate N	lature of Notice	Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG	AND ABANDON	REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON 🔲 CHAN	GE PLANS	COMMENCE DRI	ILLING OPNS.□ P AND A 🛛
PULL OR ALTER CASING MULT	IPLE COMPL 🔲	CASING/CEMENT	T JOB 🔲
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1. 6/1/12-MIRU. POOH w/2-3/8" tbg. Tag existing CIBP @ 11850'. 9.5# mud is circulated between cement plugs.			
2. Spot 25 sx cmt on CIBP @ 11850'.			
3. Spot 25 sx cmt @ 8616'.			
4. Spot 25 sx cmt @ 8091'. (Abo top @ 8086'.)			
5 Pulled 5-1/2" casing from ~6045'.			
6. Spot 45 sx stub plug @ 6093'. Tag	TOC @ 5980'.		
7. Spot 35 sx cmt @ 4946'. Tag TOC @ 4926'. Spot 45 sx cmt @ 4926'. Tag TOC @ 4778' (8-5/8" csg shoe @ 4866')			
8. Spot 35 sx cmt @ 2982'. (Salt base @ 2982'. Calc PBD @ 2847')			
9. Spot 35 sx cmt @ 2096'. (Salt top @ 2096'. Calc PBD @ 1961')			
10. Spot 45 sx cmt @ 622'. Tag TOC @ 470'. (13-3/8" csg shoe @ 543')			
 11. Spot 35 sx cmt from 131' to surface. 12. 6/29/12-Wellhead cut off, and dry hole marker has been set. Wellbore plugged & abandoned. 			
12. $\underline{6/29/12}$ -Wellhead cut off, and dry h	ole marker has been set.		
		•	Approved for plugging of well bore only. Liability under bond is retained pending receipt
Spud Date:	Die Delege D	1	of C-103 (Subsequent Report of Well Plugging)
Spud Date.	Rig Release Da	1 1	which may be found at OCD Web Page under
	<u> </u>		Forms, www.cmnrd.state.nmlus/ocd.
71 1			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
β			
SIGNATURE KOMWO STACK	TITLE C	Operations Technicia	DATE 6/20/12
SIGNATURE AUTONO STUDIO	HILEC	operations recunicia	anDATE6/29/12
Type or print name _Ronnie Slack E-mail address: _Ronnie.Slack@dvn.com PHONE: 405-552-4615			
For State Use Only			
M (2Ht)			
APPROVED BY: 1 Calculation Title Compliance Office DATE 7/5/2012			
Conditions of Approval (if any):			
V		(•

