Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DI	VISION 30.025.35471 5 Indicate Type of Lease
District III	1220 South St. Francis	Dr. 5. Indicate Type of Lease STATE XX FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		0. 00 00 00 20 XX
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG B. CATION FOR PERMIT" (FORM C-101) FOR SU	ACK TO A
1. Type of Well: Oil Well XX	Gas Well Other	8. Well Number 2
2. Name of Operator		9. OGRID Number
BP America Production Company 3. Address of Operator		000778 10. Pool name or Wildcat
P.O. Box 1089, Eunice, NM 88231		Jalmat Tansil Yates SRQ Gas
4. Well Location		
Unit Letter_G:_	1780feet from theN	line and $_$ 1980 feet from the $_E$ line
Section 34	Township 22S Ran	· · · · · · · · · · · · · · · · · · ·
	11. Elevation (Show whether DR, RK)	3, RT, GR, etc.)
Pit or Below-grade Tank Application o	3489' GR r Closure □	
		water well2640' Distance from nearest surface water_> 1000'_
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction Material
		e of Notice, Report or Other Data
		t of Notice, Report of Other Data
NOTICE OF IN		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		MEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON		MMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	SING/CEMENT JOB
OTHER:		HER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
or recompletion.		32345676
		A 100
TD: 3700' PBD: 3609' PERFS: 3005-3552'		
TD: 3700' PBD: 3609' PERFS: 3005-3552' MIRUPU. LDPMP & RODS. INSTALL BOP & POH W/TBG. RIH W/CSG SCRAPER & BIT TO 3000'. POH.		
MIRUPU. LDPMP & RODS. INSTALL BOP & POH W/TBG. RIH W/CSG SCRAPER & BIT TO 3000'. POH.		
RUWL. SET CIBP @ 2955'. (50' ABOVE TOP PERF @3005'). DUMP 35' CMT W/BAILER. RDWL.		
RIH W/1BG 10 2950'. LOAD CSG & 1ES1 10 500#. DISPLACE HOLE W/9.0# SAL1 GEL W/12,5# PER BBL		
	CMT ACROSS SALT ZONE. WOC A	ND TAG.
LD TO 500'. CIRC CMT TO SURF	. POH LOAD CSG.	65521202125
CUT OFF WH AND INSTALL PA	MARKER.	
CUT OFF ANCHORS		E OIL CONSERVATION DIVISION MUST
WELL PA	B	E NOTIFIED 24 HOURS PRIOR TO THE
	RF	GINNING OF DI LICOING OPER LEGISLE
		GINNING OF PLUGGING OPERATIONS.
I hereby certify that the information	above is true and complete to the best o	f my knowledge and belief. I further certify that any pit or below-
SIGNATURE TOURS	closed according to NMOCD guidelines [], a [eneral permit 🔲 or an (attached) alternative OCD-approved plan 🔲.
Journal Jacob		eneral permit or an (attached) alternative OCD-approved plan DATE 04.27.05
7	Muustitle so	DATE04.27.05
Type or print name Kellie D. Murr For State Use Only	Muustitle so	
Type or print name Kellie D. Mur	rish E-mail address: murri	DATE04.27.05

WELLBORE SCHEMATIC

