Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 OH CONSEDVATION DRUSION	30-025-05861
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 MOBBS OCH. CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Biazos Rd, Aztec, NM 87410	6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM JUL 2 3 2012 87505	B 2657
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPONED FOR THE PROPONED AND THE PROPONED AND THE PROPONED AND THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY (FORM C-101) FOR SUCH	East Eumont Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection	8. Well Number 121
2. Name of Operator	9. OGRID Number 192463
OXY USA WTP Limited Partnership	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	Eumoral Tates TRQN
4. Well Location Unit Letter <u>O</u> : <u>660</u> feet from the <u>south</u> line and <u>1980</u> feet from the <u>east</u> line	
Section 2 Township 205 Range 37E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3605'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A OPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
DOWNHOLE COMMINGLE	
	-MIT-TA Status A
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
7/5/12 MIRU PU, work on WH	
7/6/12 Continue to work on WH, RUWL, RIH to cut tbg above pkr, could only get 100' into hole, RDWL. NDWH, RIH w/	
spear, pull on tbg until pkr sheared, POOH w/ 1 jt, NU BOP. 7/7/12 POOH w/ tbg & pkr, RIH w/ bit & scraper to clean csg. POOH w/ bit & scraper. RIH & set CIBP @ 3650', test to	
500#, held good. Circ hole w/ pkr fluid.	
7/9/10 Top off csg w/ pkr fluid, POOH w/ tbg, NDBOP, NEWH, test csg to 500#, held OK, RDPU.	
7/19/10 Run MIT test to 540# for 30 min, held OK. Maxey Brown-NMOCD notified	
This Approval of Temporary 10 70/3	
Abandonm ent Expires	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE In TITLE Regulatory Advisor DATE 7/20/12	
Type or print name E-mail address: <u>david_stewart@oxy.com</u> PHONE:432-685-5717	
For State Use Only	
APPROVED BY Angehr TITLE Dist. Mar DATE 7-23-2012	
Conditions of Approval (if any)	

-



OXY USA WTP LP - Current East Eumont Unit #121 API No. 30-025-05861



. .

.

11" hole @ 318' 8-5/8" csg @ 318' w/ 300sx-TOC-Surf-Circ

7-7/8" hole @ 3849' 5-1/2" csg @ 3848' w/ 1220sx-TOC-180-TS

Perfs @ 3700-3816'

CIBP @ 3650'