# H<sub>2</sub>S Contingency Plan Pearsall Federal SWD #1

Cimarex Energy Co. of Colorado Unit E, Section 28 T17S-R32E, Lea County, NM **HOBBS OCD** 

AUG 0 1 2012

RECEIVED

### **Emergency Procedures**

In the event of a release of gas containing H<sub>2</sub>S, the first responder(s) must:

- ★ Isolate the area and prevent entry by other persons into the 100 ppm ROE.
- ★ Evacuate any public places encompassed by the 100 ppm ROE.
- **★** Be equipped with H<sub>2</sub>S monitors and air packs in order to control the release.
- ★ Use the "buddy system" to ensure no injuries occur during the response.
- ★ Take precautions to avoid personal injury during this operation.
- ★ Contact operator and/or local officials to aid in operation. See list of phone numbers attached.
- **★** Have received training in the:
  - Detection of H₂S, and
  - ♦ Measures for protection against the gas,
  - Equipment used for protection and emergency response.

#### **Ignition of Gas Source**

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO<sub>2</sub>). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally, the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever there is an ignition of the gas.

### Characteristics of H<sub>2</sub>S and SO<sub>2</sub>

Common	Chemical	Specific	Threshold	Hazardous	Lethal
Name	Formula	Gravity	Limit	Limit	Concentration
Hydrogen Sulfide	H₂S	1.189 Air=1	10 ppm	100 ppm/hr	600 ppm
Sulfur Dioxide	SO <sub>2</sub>	2.21 Air=1	2 ppm	N/A	1000 ppm

#### **Contacting Authorities**

Cimarex Energy Co. of Colorado's personnel must liaise with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available including directions to site. The following call list of essential and potential responders has been prepared for use during a release. Cimarex Energy Co. of Colorado's response must be in coordination with the State of New Mexico's "Hazardous Materials Emergency Response Plan" (HMER).

## H₂S Contingency Plan Emergency Contacts

#### Pearsall Federal SWD #1

Cimarex Energy Co. of Colorado Unit E, Section 28 T17S-R32E, Lea County, NM

Cimarex Energy Co. of Colorad	lo	800-969-4789	
Co. Office and After-Hours Me	enu		
Key Personnel			
Name	Title	Office	Mobile
Larry Seigrist	Drilling Manager	432-620-1934	580-243-8485
Scott Lucas	Field Super		432-894-5572
Roy Shirley	Field Super		432-634-2136

Ambulance	911		
State Police	575-746-2703		
City Police	575-746-2703		
Sheriff's Office	575-746-9888		
Fire Department	575-746-2701		
Local Emergency Planning Committee	575-746-2122		
New Mexico Oil Conservation Division	575-748-1283		
<u>Carlsbad</u>			
Ambulance	911		
State Police	575-885-3137		
City Police	575-885-2111		
Sheriff's Office	575-887-7551		
Fire Department	575-887-3798	1	
Local Emergency Planning Committee	575-887-6544		
US Bureau of Land Management	575-887-6544	1	
Santa Fe New Mexico Emergency Response Commission (Santa Fe) New Mexico Emergency Response Commission (Santa Fe) 24 Hrs	505-476-9600 505-827-9126		
New Mexico Emergency Response Commission (Santa Fe) 24 Hrs New Mexico State Emergency Operations Center	505-827-9126 505-476-9635		
National			
National Emergency Response Center (Washington, D.C.)	800-424-8802		
Medical			
Flight for Life - 4000 24th St.; Lubbock, TX	806-743-9911	-	
Aerocare - R3, Box 49F; Lubbock, TX	806-747-8923		
Med Flight Air Amb - 2301 Yale Blvd S.E., #D3; Albuquerque, NM	505-842-4433		
SB Air Med Service - 2505 Clark Carr Loop S.E.; Albuquerque, NM	505-842-4949		
<u>Other</u>			
Boots & Coots IWC	800-256-9688	or	281-931-8884
Cudd Pressure Control	432-699-0139	or	432-563-3356
Halliburton	575-746-2757		




Exhibit D-1
Injection Facilities Layout Diagram
Pearsall Federal SWD #1
Cimarex Energy Co.
28-175-32E
SHL 2303 FNL & 1260 FWL
Eddy County, NM

