Submit 3 Copies To Appropriate District	State of New	Mexico	J	Form C-103
Office District I	Energy, Minerals and	Natural Resources		May 27, 2004
1625 N French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W Grand Ave., Artesia, NM 88270  BEST OF THE CONSERVATION DIVISION		WELL API NO.		
1301 W Grand Ave., Artesia, NM 88210	BBS OIL CONSERVAT	ION DIVISION	30-025-09224  5. Indicate Type of Lease	
Destrict III	1000 0 - 41 04	Francis Dr.	STATE FEE	: n
District IV	G 0 8 2012 South St. Santa Fe, NI	M 87505	6. State Oil & Gas Lease No.	
1220 S St. Francis Dr , Santa Fe, NM 87505	_			
	REPORTS ON WE	ELLS	7. Lease Name or Unit Agree	ment Name
(DO NOT USE THIS FORM FOR PROPO			MEXICO E. COM	′
DIFFERENT RESERVOIR. USE "APPL PROPOSALS)	ICATION FOR PERMIT" (FORM C-1	01) FOR SUCH		
1. Type of Well: Oil Well	Gas Well 🗌 Other		8. Well Number 1	
2. Name of Operator ENERVEST OPERA	TING LLC		9. OGRID Number 143199	
3. Address of Operator			10. Pool name or Wildcat	
1001 FANNINX STE. 800 HOUS	TON TX 77002		JALMAT-TAN-Y-SR (GAS)	) /
4. Well Location				
Unit Letter O :660_feet	from the $\_SOUTH\_$ line and 13	320_feet from the EAST	T line /	-
Section 2 Township 23			LEA 🗸	
The same of the same of the same of the same of the same	11. Elevation (Show whether	r DR, RKB, RT, GR, etc	(1)	
Pit or Below-grade Tank Application	or Closure	<u> </u>		
		esh water well - Distan	ce from nearest surface waterN/A	
Pit Liner Thickness: mil	Below-Grade Tank: Volume		ruction Material	
12. Check	Appropriate Box to Indica	ie maiure of monce	, Report of Other Data	
NOTICE OF I	NTENTION TO:	į   Sl	JBSEQUENT REPORT (	OF:
PERFORM REMEDIAL WORK $\Box$	<del>-</del>		<del></del>	IG CASING □
TEMPORARILY ABANDON				
			P AND A P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEME	<del></del>	
		CASING/CEME	<del></del>	
PULL OR ALTER CASING	MULTIPLE COMPL  d operations. (Clearly state all p	CASING/CEME OTHER:	ENT JOB	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com	CASING/CEME OTHER: ertinent details, and give appletions: Attach wellbook	ENT JOB	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,840	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com  circulate hole mud spot 30s	CASING/CEME OTHER: ertinent details, and gives a cmt.	ENT JOB	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,840 2. 7/24/12 Perf @ 1,600' sqz	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com	cASING/CEME OTHER: ertinent details, and giv appletions: Attach wellb  xs cmt.  Approx.	re pertinent dates, including estimore diagram of proposed complet	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,846 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 1,318' sqz 4. 7/25/12 Perf @ 300' sqz 3	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com c circulate hole mud spot 30sz 55 sxs cmt WOC & tag 1,460 z 150 sxs cmt WOC & tag 1,18 30 sxs cmt WOC & tag 180'.	cASING/CEME OTHER:  ertinent details, and giv appletions: Attach wellb  as cmt.  3.  Approv	e pertinent dates, including estimore diagram of proposed complet	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,844 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 1,318' sqz 4. 7/25/12 Perf @ 300' sqz 3. 7/26/12 Perf @ 60' circul	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com circulate hole mud spot 30ss 55 sxs cmt WOC & tag 1,460 50 sxs cmt WOC & tag 1,18 60 sxs cmt WOC & tag 180°. ate 35 sxs cmt to surface.	casing/ceme OTHER:  ertinent details, and giv apletions: Attach wellbox  as cmt.  30'.  Approv Liability of C-10 which in	re pertinent dates, including estimore diagram of proposed complet ed for plugging of well bore only.  y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) nay be found at OCD Web Page under	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,846 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 1,318' sqz 4. 7/25/12 Perf @ 300' sqz 3	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com c irculate hole mud spot 30ss c 55 sxs cmt WOC & tag 1,460 c 150 sxs cmt WOC & tag 1,18 d sxs cmt WOC & tag 180°. ate 35 sxs cmt to surface.	casing/ceme OTHER:  ertinent details, and giv apletions: Attach wellbox  as cmt.  30'.  Approv Liability of C-10 which in	e pertinent dates, including estimore diagram of proposed complet	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,844 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 1,318' sqz 4. 7/25/12 Perf @ 300' sqz 3. 7/26/12 Perf @ 60' circul	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com circulate hole mud spot 30ss 55 sxs cmt WOC & tag 1,460 50 sxs cmt WOC & tag 1,18 60 sxs cmt WOC & tag 180°. ate 35 sxs cmt to surface.	casing/ceme OTHER:  ertinent details, and giv apletions: Attach wellbox  as cmt.  30'.  Approv Liability of C-10 which in	re pertinent dates, including estimore diagram of proposed complet ed for plugging of well bore only.  y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) nay be found at OCD Web Page under	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,844 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 1,318' sqz 4. 7/25/12 Perf @ 300' sqz 3. 7/26/12 Perf @ 60' circul	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com circulate hole mud spot 30ss 55 sxs cmt WOC & tag 1,460 50 sxs cmt WOC & tag 1,18 60 sxs cmt WOC & tag 180°. ate 35 sxs cmt to surface.	casing/ceme OTHER:  ertinent details, and giv apletions: Attach wellbox  as cmt.  30'.  Approv Liability of C-10 which in	re pertinent dates, including estimore diagram of proposed complet ed for plugging of well bore only.  y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) nay be found at OCD Web Page under	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,844 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 1,318' sqz 4. 7/25/12 Perf @ 300' sqz 3. 7/26/12 Perf @ 60' circul	MULTIPLE COMPL  d operations. (Clearly state all p RULE 1103. For Multiple Com circulate hole mud spot 30ss 55 sxs cmt WOC & tag 1,460 50 sxs cmt WOC & tag 1,18 60 sxs cmt WOC & tag 180°. ate 35 sxs cmt to surface.	casing/ceme OTHER:  ertinent details, and giv apletions: Attach wellbox  as cmt.  30'.  Approv Liability of C-10 which in	re pertinent dates, including estimore diagram of proposed complet ed for plugging of well bore only.  y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) nay be found at OCD Web Page under	nated date of
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,846 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 300' sqz 3. 5. 7/26/12 Perf @ 60' circul 6. Cut and Cap well install	d operations. (Clearly state all p RULE 1103. For Multiple Com  of circulate hole mud spot 30ss of 55 sxs cmt WOC & tag 1,460 of 150 sxs cmt WOC & tag 1,18 of sxs cmt WOC & tag 180°. ate 35 sxs cmt to surface. dry hole marker.	casing/ceme other: ertinent details, and given apletions: Attach wellboxs cmt. ''. 30'. Approve Liability of C-10. which means.	re pertinent dates, including estimore diagram of proposed complet ed for plugging of well bore only. Younder bond is retained pending receipt 3 (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/oed,	nated date of ion or
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,844 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 1,318' sqz 4. 7/25/12 Perf @ 300' sqz 3. 7/26/12 Perf @ 60' circul	d operations. (Clearly state all p RULE 1103. For Multiple Come of the composition of the	casing/ceme other:  criment details, and given pletions: Attach wellboxs cmt.  Approving Liability of C-10, which in Forms, the best of my knowled.	re pertinent dates, including estime ore diagram of proposed completed for plugging of well bore only.  Younder bond is retained pending receipt a (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/ose.	nated date of ion or
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,840 2. 7/24/12 Perf @ 1,600' sqz 3 3. 7/25/12 Perf @ 300' sqz 3 5. 7/26/12 Perf @ 60' circul 6. Cut and Cap well install	d operations. (Clearly state all p RULE 1103. For Multiple Come of the composition of the	casing/ceme other:  criment details, and given pletions: Attach wellboxs cmt.  Approving Liability of C-10.  which makes the best of my knowledgines \( \times \), a general permit [	re pertinent dates, including estime ore diagram of proposed completed for plugging of well bore only.  Younder bond is retained pending receipt a (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/ose.	nated date of ion or
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,840 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 300' sqz 3. 7/25/12 Perf @ 300' sqz 3. 5. 7/26/12 Perf @ 60' circul 6. Cut and Cap well install  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	d operations. (Clearly state all p RULE 1103. For Multiple Com.) circulate hole mud spot 30s; 55 sxs cmt WOC & tag 1,460; 150 sxs cmt WOC & tag 1,80; ate 35 sxs cmt to surface. dry hole marker.	casing/ceme other:  criment details, and given pletions: Attach wellboxs cmt.  Approving Liability of C-10.  which makes the best of my knowledgines \( \times \), a general permit [	re pertinent dates, including estime ore diagram of proposed completed of the plugging of well bore only.  Younder bond is retained pending receipt a (Subsequent Report of Well Plugging) has be found at OCD Web Page under www.cmnrd.atate.nm.us/osd.  ge and belief. I further certify that a or an (attached) alternative OCD-app.  (Basic Energy Services) DATE	any pit or below-proved plan .
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,840 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 300' sqz 3. 7/25/12 Perf @ 60' circul 6. Cut and Cap well install  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name:	d operations. (Clearly state all p RULE 1103. For Multiple Com  'circulate hole mud spot 30s; 55 sxs cmt WOC & tag 1,460; 150 sxs cmt WOC & tag 1,18 30 sxs cmt WOC & tag 180'. ate 35 sxs cmt to surface. dry hole marker. 7-24-	casing/ceme other:  criment details, and given pletions: Attach wellboxs cmt.  Approving Liability of C-10.  which makes the best of my knowledgines \( \times \), a general permit [	re pertinent dates, including estime ore diagram of proposed completed for plugging of well bore only.  Younder bond is retained pending receipt a (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/oed.  ge and belief. I further certify that a or an (attached) alternative OCD-appears.	any pit or below-proved plan .
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,840 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 300' sqz 3. 7/25/12 Perf @ 300' sqz 3. 5. 7/26/12 Perf @ 60' circul 6. Cut and Cap well install  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	d operations. (Clearly state all p RULE 1103. For Multiple Com.) circulate hole mud spot 30s; 55 sxs cmt WOC & tag 1,460; 150 sxs cmt WOC & tag 1,80; ate 35 sxs cmt to surface. dry hole marker.	casing/ceme other:  criment details, and given pletions: Attach wellboxs cmt.  Approving Liability of C-10.  which makes the best of my knowledgines \( \times \), a general permit [	re pertinent dates, including estimore diagram of proposed complet ed for plugging of well bore only.  y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/oed.  ge and belief. I further certify that a or an (attached) alternative OCD-app (Basic Energy Services) DATE  Telephone No. 432-563-3355	any pit or below-proved plan .
PULL OR ALTER CASING OTHER: -1.  13. Describe proposed or complete starting any proposed work). SEE recompletion.  1. 7/23/12 Tag plug @ 2,840 2. 7/24/12 Perf @ 1,600' sqz 3. 7/25/12 Perf @ 300' sqz 3. 7/25/12 Perf @ 60' circul 6. Cut and Cap well install  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name:	d operations. (Clearly state all p RULE 1103. For Multiple Com.) circulate hole mud spot 30s; 55 sxs cmt WOC & tag 1,460; 150 sxs cmt WOC & tag 1,80; ate 35 sxs cmt to surface. dry hole marker.	casing/ceme other:  ertinent details, and give appletions: Attach wellbe as cmt.  i.  i.  i.  i.  i.  i.  i.  i.  i.	re pertinent dates, including estimore diagram of proposed complet ed for plugging of well bore only.  y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/oed.  ge and belief. I further certify that a or an (attached) alternative OCD-app (Basic Energy Services) DATE  Telephone No. 432-563-3355	any pit or below-proved plan .