

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OGD**  
**AUG 22 2012**

**OIL CONSERVATION DIVISION**  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-32128
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2656
7. Lease Name or Unit Agreement Name HARDY 36 STATE
8. Well Number 01
9. OGRID Number 217817
10. Pool name or Wildcat SOUTH CASS STRAWN/MCKEE
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3489' GL

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator ConocoPhillips Company
3. Address of Operator P. O. Box 51810 Midland, TX 79710
4. Well Location Unit Letter K : 1980 feet from the SOUTH line and 2230 feet from the WEST line Section 36 Township 20S Range 37E NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3489' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: TEST STRAWN PRODUCTION ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Unhang well. POOH w/ rods & pump. ND WH NU BOP. POOH w/ tbg. RIH w/ RBP set @ 7760' & pkr @ 7718' to test RBP- held. Release pkr & LD. Drop 200# sand down csg. TIH w/ 237 jts, 2 7/8", 6.5#, L-80 tbg reset @ 7719'. ND BOP NU WH. RIH w/ rods & pump. Hung well. RDMO 7/24/2012

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Ashley Martin*

TITLE Staff Regulatory Technician

DATE 08/15/2012

Type or print name Ashley Martin

E-mail address: Ashley.Martin@conocophillips.com PHONE: (432)688-6938

**For State Use Only**

APPROVED BY

*[Signature]*

TITLE

*Dist. Reg.*

DATE

*8-28-2012*

Conditions of Approval (if any):

AUG 28 2012