Office	tate of New Me	<del>-</del>		Form	
<u>District 1</u> – (575) 393-6161 Energy, N	linerals and Natur	ral Resources	WELL ADINO	Revised August	1, 2011
1625 N French Dr., Hobbs, NM 88240  District II – (575) 748-1283			WELL API NO. 30-025-20358		
District II - (575) 748-1283 811 S First St., Artesia, NM 88210 District III - (505) 334-6178 District III - (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of	Lease	
District III – (505) 334-6178 1220 South St. Francis Dr.			STATE 🖂		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460  Santa Fe, NM 87505			6. State Oil & Gas I		
District III – (505) 334-6178			AO-1469		
61303			7. Lease Name or U	Jnit Agreement N	Vame
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSAGE CONTROL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			.,		
DIFFERENT RESERVOIR. USE "APPLICA"TION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Apache State "Q"	/	
1. Type of Well: Oil Well 🔀 Gas Well 🔲 Other			8. Well Number	4	
2. Name of Operator			9. OGRID Number	873	
Apache Corporation					
3. Address of Operator			10. Pool name or W	/ildcat	
303 Veterans Airpark Lane, Ste. 3000, Midland, Texas 79705			Weir; Blineberry		
4. Well Location					
Unit LetterI:1980	_feet from the	_S line and	_660_feet from the _	Eli	ne
Section 16 Township 20S Range 37E NMPM County Lea					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3550' DF					
12. Check Appropriate Bo	ox to Indicate Na	ature of Notice, I	Report or Other D	ata	
NOTICE OF INTENTION TO	O. 1	l cupo		ODT OF	
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK ☐ PLUG AND A	SEQUENT REPORT NEPORT	UR I UF. LTERING CASIN	vic $\square$		
				' AND A	
TEMPORARILY ABANDON				AND A	Ц
PULL OR ALTER CASING  MULTIPLE CO	NVIPL LI	CASING/CEMENT	10B 🗆		
DOWNTOLL COMMININGLE					
OTHER:		OTHER:			
13. Describe proposed or completed operations.	(Clearly state all p		give pertinent dates,	including estima	ated date
of starting any proposed work). SEE RULE	. 19.15.7.14 NMAC	C. For Multiple Com	pletions: Attach wel	llbore diagram of	f
proposed completion or recompletion.					
(100/10 MIDVIN W 11 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1 /4 1550	CD111 / 4 0 / 40 1 1 . 0	60.1/02.1.11	11 0
6/22/12 MIRU Mesa Well Service unit, NI					
tag CIBP @ 5065'. Est. circ., drill & push CIBP to 60 ND BOP, NU WH. Prepare to P&A well.	2/8'. Circ. Clean, 1	oon & LD tog. MIR	to Rotary w L & set	CIBP @ 6230°.	KDMO.
ND BOP, NO WH. Prepare to P&A well.					
				٦	
Spud Date:	Rig Release Da	te:			
	C			_	
I hereby certify that the information above is true and	complete to the be	st of my knowledge	and belief.		
	•	, ,			
$\mathcal{A}$ · $\mathcal{A}$ ·					
SIGNATURE OWN DUM	TITLE Reclar	mation Foreman	DATE08/27/1	2	
·· · · — — — — — — — — — — — — — — — —	ess: <u>guinn.burks@a</u>	apachecorp.com	PHONE: 432-55	6-9143	
For State Use Only	1 -			_	
APPROVED BY:	LITTE DE	t m	DATI	8-29-2	2017
Conditions of Approval (if any):					UL
				AUG 2 9 201	19
			•		