<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240		State of New Mexico	Form C-1
Phone (575) 393-6161 1ax (575) 393-0720 District II	HOBBS OCD	Energy Minerals and Natural Resources	Revised August 1, 20
		Oil Conservation Division	Permit
1000 Rio Brazos Road Aztec NM 87410 Phone (505) 334-6178 Fax (505) 334-6170	SEP 1 8 2012	1220 South St. Francis Dr.	
District IV 1220 S St Francis Dr. Santa Fe. NM 87505 Phone (505) 476-3460 Fax. (505) 476-3462	RECEIVED	Santa Fe. NM 87505	
APPLICATION		FO DRILL, RE-ENTER, DEEPEN, PLUG	GBACK, OR ADD A ZONE

Merit Er 13727 N Dallas, T	nergy Cor loel Rd. S FX 75240	npany Ste. 500	·							-		14591 ^^i 025-29	PI Numbe	r
⁴ Prop 30723 2	erty Code 394	48	Peo	oples 32 S	tate		Property N	ame			,		• w 1	/ell No
						7	Surface	e Locatio	n					
UL - Lot	Section	Township		Range	Lo	ət Idn	Feet fic	an N	/S Line	F F	eet From	E/	/W Line	County
Р	32	18S	3	SE			660	Sout	h	660		East		Lea
	····	• • • • • • • • • • • • • • • • • • •				8	Pool In	formatio	n					
Scharb; Que	een													
		<u></u>				Additi	ional W	ell Infor	nation					
° Wor	k Type		10 -	Well Type		Auun	¹¹ Cable/Re			12 Leas	е Туре		¹³ Gro	ound Level Elevation
Re-Enter	21	Oil				Rotary	V	·	State				3920	
	ultiple	690		posed Depth		¹⁶ Formation Queen			¹⁷ Contractor			¹⁸ Spud Date 09/27/2012		
Depth to Groui				nce from				Distance to nearest surface water						
				19	Prop	osed	Casing	and Cem	ent Pro	ograi	n			
Туре	Hol	e Size	Casi	ng Size	C	asing We	eight/ft	Settir	g Depth		Sacks of	Cement		Estimated TOC
Surf	17.5	1	3.375		54.5			395		4	00		Su	urf.
Intl	12.25	8	.625		28			3900		1	550		Su	ırf.
Prod	7.875	5	.5		17			6907		0				
	1				1			1		1				

Casing/Cement Program: Additional Comments

		Permit Expi	res 2 Years From Approval less Drilling Underway
	Proposed Blowe	out Prevention Program	
Туре	Working Pressure	Test Pressure	Manufacturer
Double Ram	3000	5000	Townsend

of my knowledge and belief. I further certify that the dril	ation given above is true and complete to the ling pit will occurstructed according to	OIL CONSERVATION DIVISION
NMOCD guidelines ⊠, a ge OCD-approved plan □.	neral permit [], or an (attached) alternativ	Approved By.
Printed name: Matt Ogden	0	Title: retroleum Engineer
Title: Regulatory Analyst		Approved Date:
E-mail Address: matt.ogden	@meritenergy.com	SEP 202012
Date: 09/17/2012	Phone (972)628-1603	Conditions of Approval Attached

Form C-101

Merit Energy Company 3920 " Surface Location Section Township Feet from the North/South line Feet from the East/West line Range Lot Idn 32 18S 3SE 660 South 660 East "Bottom Hole Location If Different From Surface Lot Idn Feet from the North/South line Feet from the Section Township Range East/West line 15 Order No. 12 Dedicated Acres ¹³ Joint or Infill 14 Consolidation Code

411 × 11 1.44 alidatad .:+ 1. ما المريد ال . 11 . 1 . 1..... L 1 1 1 1. 1 1.

16	"OPERATOR CERTIFICAT	
	Thereby certify that the information contained herein is true	
	to the best of my knowledge and belief, and that this organize	
	owns a working interest or unleased mmeral interest in the le the proposed bottom hole location r has a right to drill this	-
	the proposed boliam note tocation or nex a right to an in this location pursuant to a contract with an owner of such a mini-	
	interest or to a valuation provident as with our owner of start a mine	
	ander her etafare entered hy Haydrission	. /
··	 	
		7/2012
	Matt Ogden	
	Printed Name	
	matt.ogden@meritenergy.com	
	E-mail Address	
	SURVEYOR CERTIFICAT	ION
	I hereby certify that the well location shown	on this
	plut was plotted from field notes of actual su	IIveys
	made by me or under my supervision, and the	at the
	sume is true and correct to the best of my be	lief
		,
	Date of Survey	
	Signature and Seal of Professional Surveyor.	
	#1	
	Certificate Number	,

¹ API Number ² Pool Code ³ Pool Name 55630 Scharb; Queen

⁵ Property Name

⁸ Operator Name

strict III	1220 South St. Francis Dr.
00 Rio Biazos Road. Aztec, NM §7446 1 8 2012	1220 South St. 1141015 D1.
00 Rio Biazos Road, Aziec, NM 87410, 1 8 2012	Santa Fe, NM 87505
<u>strict IV</u>	Sana 10, INIVI 87505
20 S. St. Francis Dr., Santa Fe, NM 87505	
one (505) 476-3460 Lax (505) 476-3462	LOCATION AND ACREAGE DEDICATION PLAT
WELL	. LOCATION AND ACREAGE DEDICATION PLAT

AMENDED REPORT

District I

<u>D15</u>

30-025-29121

307232

14591

UL or lot no.

UL or lot no.

40

Р

⁴ Property Code

⁷OGRID No.

100 Pho

Dis 122 Ph

Peoples 32 State

District II Resources Department OIL CONSERVATION DUMENT District III

⁶ Well Number

⁹ Elevation

Lea

County

County

1



Merit Energy Company 13727 Noel Road, Suite 500 Dallas, TX 75240

Date: September 17, 2012

To: New Mexico Oil Conservation Division

Attention: Donna Mull

RE. Drilling Permit to Re-Enter – Location Never Released Lea County, New Mexico

<u>Merit Energy Company</u> has requested approval to Re-Enter the Peoples 32 State, API # 30-025-29121, located in Lea County, NM, Sec 32 18S 35E. The well was plugged in 2005 by Forest Oil, but the location was never released. We accept responsibility of remediating the surface location when the well is plugged at a future date.

Please let me know if you have any questions.

Sincerely,

Matt Ogden Regulatory Analyst Phone: 972-628-1603 Fax: 972-682-1903

District I = (575) 393-6161 Energ	State of New Mexico		Form C-10			
$\frac{1015(1)(11-(575))595(0101)}{1015(101-(575))595(0101)}$	gy, Minerals and Natural R	esources	Revised August 1, 20			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 HOBBS OCD	CONCEDUATION DI	1	API NO. 30-025-29121			
811 S. First St., Artesia, NM 88210 OIL	CONSERVATION DIV 1220 South St. Francis I	5. Ind	cate Type of Lease			
1000 Rio Brazos Rd., Aztec, NMCPP 18 ZUIL	Santa Fe, NM 87505		STATE S FEE			
<u>District IV</u> – (505) 476-3460 1220 S St Francis Dr., Santa Fe, NM	Santa PC, INIVI 87505		e Oil & Gas Lease No.			
87505 SUNDRY NORES AND F		307232				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRI DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS)	LL OR TO DEEPEN OR PLUG BA	CK TO A Peoples	se Name or Unit Agreement Name 32 State			
1 Type of Well: Oil Well X Gas Well	Other	8. We	8. Well Number 1			
2. Name of Operator Merit Energy Company		9. OG	RID Number 14591			
3. Address of Operator 13727 Noel Road, Ste.	10. Pc	10. Pool name or Wildcat				
Dallas, TX 75240		Scharb; Queen				
4. Well Location]				
Unit Letter P : 660	feet from the S	line and <u>660</u>	feet from the Elin			
	Township 18S Range		1 County Lea			
and the second	tion (Show whether DR, RKB	, <i>RT</i> , <i>GR</i> , <i>etc.</i>)	And the second se			
3920' GR						
TEMPORARILY ABANDON	PLANS COI	MEDIAL WORK MMENCE DRILLING C SING/CEMENT JOB	ALTERING CASING [PNS. P AND A			
OTHER. Re-Enter		IER]			
 Describe proposed or completed operation of starting any proposed work). SEE R proposed completion or recompletion. 	ULE 19.15.7.14 NMAC. Fo	Multiple Completion:	s: Attach wellbore diagram of			
The was plugged in 2005 by Forest Oil. The	5-1/2" casing was cut @ 4050)', and several cement i	lugs were numped from there to			
surface. We plan to drill out all cement plugs $1/2$ " casing down to where the casing was cut. attached.	using a workover rig, clean of	lown to the cement abo	ve the retainer @ 6907', then run 5			
1/2" casing down to where the casing was cut. attached.	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut.	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached.After we have 5-1/2" casing in place, we'll squ	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached.After we have 5-1/2" casing in place, we'll squ	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached.After we have 5-1/2" casing in place, we'll squ	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached.After we have 5-1/2" casing in place, we'll squ	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached.After we have 5-1/2" casing in place, we'll squ	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached.After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation.	using a workover rig, clean of We'll latch on with a lead-su	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached.After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation.	using a workover rig, clean o We'll latch on with a lead-st ueeze cement behind the casin	lown to the cement abo yle casing patch and th	ve the retainer @ 6907', then run 5 e final wellbore configuration is			
1/2" casing down to where the casing was cut. attached. After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation. Spud Date:	using a workover rig, clean of We'll latch on with a lead-st neeze cement behind the casin Rig Release Date:	lown to the cement abo yle casing patch and th ng, then run a CBL to e	ve the retainer @ 6907', then run 5 e final wellbore configuration is nsure good cement integrity, then			
1/2" casing down to where the casing was cut. attached. After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation. Spud Date:	using a workover rig, clean of We'll latch on with a lead-st neeze cement behind the casin Rig Release Date:	lown to the cement abo yle casing patch and th ng, then run a CBL to e	ve the retainer @ 6907', then run 5 e final wellbore configuration is nsure good cement integrity, then			
1/2" casing down to where the casing was cut. attached. After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation. Spud Date: hereby certify that the information above is true	using a workover rig, clean of We'll latch on with a lead-st neeze cement behind the casin Rig Release Date:	lown to the cement abo yle casing patch and th ng, then run a CBL to e	ve the retainer @ 6907', then run 5 e final wellbore configuration is nsure good cement integrity, then			
1/2" casing down to where the casing was cut. attached. After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation. Spud Date: hereby certify that the information above is true	using a workover rig, clean of We'll latch on with a lead-st neeze cement behind the casin Rig Release Date:	lown to the cement abo yle casing patch and th ng, then run a CBL to e my knowledge and bel	ve the retainer @ 6907', then run 5 e final wellbore configuration is nsure good cement integrity, then			
1/2" casing down to where the casing was cut. attached. After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation. Spud Date: hereby certify that the information above is true SIGNATURE	using a workover rig, clean of We'll latch on with a lead-st neeze cement behind the casin Rig Release Date: e and complete to the best of TITLE Regulatory A	lown to the cement abo yle casing patch and th ng, then run a CBL to e my knowledge and bel	ve the retainer @ 6907', then run 5 e final wellbore configuration is nsure good cement integrity, then 			
1/2" casing down to where the casing was cut. attached. After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation. Spud Date: hereby certify that the information above is true GIGNATURE ype or print name Matt Ogden	using a workover rig, clean of We'll latch on with a lead-st neeze cement behind the casin Rig Release Date: e and complete to the best of TITLE Regulatory A	lown to the cement abo yle casing patch and th ng, then run a CBL to e my knowledge and bel	ve the retainer @ 6907', then run 5 e final wellbore configuration is nsure good cement integrity, then			
1/2" casing down to where the casing was cut. attached. After we have 5-1/2" casing in place, we'll squ perforate and frac the Queen formation. Spud Date: hereby certify that the information above is true SIGNATURE	using a workover rig, clean of We'll latch on with a lead-st neeze cement behind the casin Rig Release Date: e and complete to the best of 	lown to the cement abo yle casing patch and th ng, then run a CBL to e my knowledge and bel	ve the retainer @ 6907', then run 5 e final wellbore configuration is nsure good cement integrity, then 			

.