

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 87249
District II
1301 W Grand Ave, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

HOBBS OGD
SEP 25 2012

CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-25116
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit
8. Well Number 311
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs; Grayburg-San Andres

SUNDRY NOTICE AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW
2. Name of Operator Occidental Permian Ltd.
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294
4. Well Location Unit Letter <u>B</u> <u>330</u> feet from the <u>North</u> line and <u>1900</u> feet from the <u>East</u> line Section <u>26</u> Township <u>18-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3685' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
OF INTENTION TO: PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> COMPL <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> P AND A <input checked="" type="checkbox"/>

13. Describe proposed or completed work, state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE or Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8-25-12 MIRU. TAG EXISTING CIBP @ 4175' 8-28-12 CIRC WELL W/ 10# MUD @ 4175'-SURFACE. 8-28-12 SPOT 25SX @ 4175'-3813' CTOC PERF @ 2855'. COULD NOT ESTABLISH. OCD MARK WHITAKER OK'ED SPOT. SPOT 25SX @ 2999'-2637' CTOC. TAG @ 2503'. 8-29-12 PERF & SQZ 50SX @ 1790'-1640' CTOC TAG @ 1539' 8-30-12 PERF & SQZ 160SX @ 425'-SURFACE. RDMO.

Spud Date:	Rig Release Date: 8/30/12
------------	---------------------------

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Mark Stephens</u>	TITLE <u>Regulatory Compliance Analyst</u>	DATE <u>9/24/12</u>
Type or print name <u>Mark Stephens</u>	E-mail address: <u>Mark.Stephens@oxy.com</u>	PHONE <u>(713) 366-5158</u>

For State Use Only	APPROVED BY <u>[Signature]</u>	TITLE <u>Dist. Mgr</u>	DATE <u>9-27-2012</u>
Conditions of Approval (if any):			

SEP 27 2012

Occidental Permian Ltd.

NHU 311-26

30-025-25116

Lea Co., NM

8 5/8" @ 353'
Cmt w/ 225 sx. Circulated

Perf at 425'. Sqz 160sx to surface

Perf at 1790'. Sqz with 50 sx

25 sx of cmt from 2637-2999'

CIBP set at 4175'. Capped with 25 sx of cmt (4175-3813')

Perforations 4220-4284'

4 1/2" @ 4329 w/ 425 sx
TOC 2770'