## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

FILE IN TRIPLICATE	OH 4	CONSERVATION DIVISION	Revised 5-27-2004
<u>DISTRICT I</u>	HOBBS OCTO	CONSERVATION DIVISION 1220 South St. Francis Dr.	WELL API NO
1625 N French Dr , Hobbs, NM 88240	a a an12	Santa Fe, NM 87505	30-025-07370
DISTRICT II 1301 W Grand Ave, Artesia, NM 88210	SEP 2 6 2012		5 Indicate Type of Lease  STATE FEE FEE
DISTRICT III			6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410	RECEIVED		
SUNDRY NO	OTICES AND REPO	ORTS ON WELLS	7 Lease Name or Unit Agreement Name
`		OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR USE	APPLICATION FOR PE	RMIT" (Form C-101) for such proposals )	North Hobbs (G/SA) Unit Section 19
1 Type of Well			8 Well No 411
Oıl Well	Gas Well	Other Injector X	
2 Name of Operator			9 OGRID No 157984
Occidental Permian Ltd.  3 Address of Operator			10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, T	X 79323		110003 (0,011)
4 Well Location			
Unit Letter A 1300	Feet From The	North 1300 Fee	et From The East Line
Section 19	Township	I8-S Range 38-1	E NMPM LEA County
	11 Elevation (Sho	w whether DF, RKB, RT GR, etc )	
	3079 DF		
Pit or Below-grade Tank Application	or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thicknessmil	Below-Grade Tank	:: Volume bbls; Construction Ma	aterial
12. Che	ck Appropriate Box	to Indicate Nature of Notice, Report, or O	Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF.			
PERFORM REMEDIAL WORK	PLUG AND ABAN	DON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completio	n CASING TEST AND CEMEN	NT JOB
OTHER Failed MIT Testing		X OTHER	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work) SEE RULE 1103 For Multiple Completions. Attach wellbore diagram of proposed completion or recompletion.			
1, Kill Well			Rule 19.15.25.14
2. Pressure test casing		Set CIBP, RB	BP or Packer within 100 feet of uppermost
3 Determine cause of casing pressure	and repair	perfs or open hol	le Pressure test to 500 psi for 30 minutes with
<ul><li>4. Secure well and rig down</li><li>5 Test casing and chart for NMOCD</li></ul>			re drop of not greater than 10% over a
6. Leave well in TA'D status		a process	30 minute period
			oo miinate penoa
I hereby certify that the information above is constructed or	true and complete to the	best of my knowledge and belief I further certify	that any pit or below-grade tank has been/will be
closed according to NMOCD guidelines	, a general	permit or an (attached) alternative	e OCD-approved
		plan	
SIGNATURE KULL		TITLE Injection Well A	Analyst DATE 9-06-2012
TYPE OR PRINT NAME Robbie Un	derhill E-r	dail address: Robert Underhill@oxy.com	<u>m</u> TELEPHONE NO 806-592-6287
For State Use Only			-
APPROVED BY	-le	TITLE LAST-Y	DATE 10-1-20/2
CONDITIONS OF APPROVAL IF ANX			and the second s
Conditions of Approval: The C	nerator shall dive	the OCD Conditions of	Approval: Notify OCD District office
District office 24 hours notice	pefore work begins	24 hours prior	to running the TATTESSATE TO
L		I	OCT 0 1 2012