<u>District 1</u> 1625 N French Dr., Hobbs, NM 88240 Phone (575) 393-6161 Fax (575) 393-0720 District 11	State of New Mexico Energy Minerals and Natural Resou	HOBBS OCD	Form C-101 Revised August 1, 2011
District II 811 S. First St., Artesia, NM 88210 Phone (575) 748-1283 Fax (575) 748-9720 District III	Oil Conservation Division	SEP 2 0 2012	Permit
1000 Rio Brazos Road, Aztec, NM 87410 Phone [,] (505) 334-6178 Fax, (505) 334-6170 District IV	1220 South St. Francis Dr.	RECEIVED	
1220 S St. Francis Dr., Santa Fe, NM 87505 Phone (505) 476-3460 Fax: (505) 476-3462	Santa Fe, NM 87505		
APPLICATION FOR PERMI	IT TO DRILL, RE-ENTER, DEEPH	EN, PLUGBACK, OI	R ADD A ZONE
Operator Name	² OGRID Nu	mber	

F

•

Celero E 400 W. Midland	Energy II, Illinois, S , TX 797	LP te. 1601 701	1								247128 API Nut 005-00688		
⁴ Property Code State 36				Property 1	Name		I	° Well No. 2					
					. <u>.</u>	⁷ Surfac	e Locatio	n			L		
UL - Lot	Section	Townsh	ıp	Range Lot Idn Feet				m N/S Line		et From	E/W Lin	e County	
0	36	125		31E 660		660	s		1980		Е	Chaves	
<u> </u>		I				⁸ Pool I	nformatic	n					
						10011							
		···											
9					Ad	lditional V		mation					
* Wor	к Туре	0		Well Type	R	¹¹ Cable/Rotary		S	¹² Lease	² Lease Type		¹³ Ground Level Elevation 4395'	
14 M	ultiple			oposed Depth				17 Contra	Contractor		¹⁸ Spud Date		
o 3055'				Queen Unassigned			gned						
Depth to Ground water 200' Est Distance			ance from ne	e from nearest fresh water well Dista			Distanc	ce to nearest surface water					
				1	⁹ Propos	ed Casing	and Cem	ient Pr	ogram	1		······································	
Туре	Hol	e Size	Cas	ing Size	Casing Weight/ft			Setting Depth			f Cement	Estimated TOC	
Surf	11"		8 5/8"		25#		294'	294'		135 sx		Surf - Calc	
?rod	7 7/8	7/8" 5 1/2"			15.5#		2990'	990' 600 sx		0 sx		253' - Calc	
										.	A Veci	L THIN ADDION	
										Exoli	es Z Yea	s From Approve	
				~ •							less Licit	- E - Lo	
						ent Progra				ents	<u> </u>	e-Entry	
Well sketc	n, well his	story &	re-entr	y procedu	re attache	d. H2S Cont	tingency Pla	in on file					
.					Propose	d Blowou	t Preventi	ion Pro	gram				
<u> </u>	Туре				Working Pre		Test Pressure			Manufacturer			
Manual			3000				1000 psi		Unassigned				

of my knowledge and belief. I further certify that the drilling p	given above is true and complete to the best it will be constructed according to	OIL CONSERVATION DIVISION				
OCD-approved plan	permit [], or an (attached) alternative	Approved By				
Printed name: Lisa Hunt		Title: Petroleum Engineer				
Title: Regulatory Analyst		Approved Date	Expiration Date:			
E-mail Address: lhunt@celeroer	ergy.com	OCT 0 3 2012				
Date: 09/18/2012	Phone: (432)686-1883	Conditions of Approval Attached				

7

District II 811 S. Enst St., Artesia Phone (575) 748-1283 District III 1000 Rio Brazos Road Phone (505) 334-6178 District IV	h61 Fax (575) 393-0720 Energy, Minerals & Natural Resources Department Revised August 1, 2011 csia, NM 88210 OIL CONSERVATION DIVISION SEP 20 2012 Submit one copy to appropriate District Office 1220 South St. Francis Dr. District Office NM 87410 Santa Fe, NM 87505 Received						Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION SEP 2 0 2012 1220 South St. Francis Dr.				
		W	ELL LC	CATIO	N AND ACI	REAGE DEDIC	CATION PLA	Т			
1	¹ API Number 30-005-00688 8559 Caprock; ³ Pool Name						ne Jeen				
⁴ Property (•		Sta	Property te 34		_		⁶ V	Vell Number 2	
⁷ OGRID 2471		Celero Energy IL, LP								Elevation 3951	
¹⁰ Surface Location											
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	e North/South line	Feet from the	East	t/West line	County	
D	36	125	3IE		660	5	1980	E		Chaves	
"Bottom Hole Location If Different From Surface											
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	e North/South line	Feet from the	East	t/West line	County	
¹² Dedicated Acre	s ¹³ Joint o	r Infill 14 Co	onsolidation	Code ¹⁵ Or	der No.						

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

16			"OPERATOR CERTIFICATION
			I hereby certify that the information contained herein is true and complete
			to the best of my knowledge and belief, and that this organization either
			owns a working interest or unleased mineral interest in the land including
			the proposed bottom hole location or has a right to drill this well at this
			location pursuant to a contract with an owner of such a mineral or working
			interest or to a voluntary pooling agreement or a compulsory pooling
			order heretofore entered by the division
			Luci Hunt 9/18/12
			Lisa Hunt
			Lisa Hunt Printed Name <u>Ihunte celero energy.</u> E-mail Address Com
	 	*	*SURVEYOR CERTIFICATION
			<i>I hereby certify that the well location shown on this</i>
		1	
			plat was plotted from field notes of actual surveys
			made by me or under my supervision, and that the
			same is true and correct to the best of my belief.
	1		
		•	Date of Survey
		•	Signature and Scal of Professional Surveyor:
		'	Signature and Scar of Trofessional Surveyor.
	<i>چ</i>		
	/ 04	1980'	
	<i>to</i>		
	6		Certificate Number
	X		
	20		(



Well History:	NCQU 1 TR 15 SEC 36O #1
(12-45) - Initial Completion:	Orig completion in open hole 2990'-3055'. Natural pumping 120 BOPD/0 BWPD 12 hour test.
<u>(9-46) - Change:</u>	Operator change to Cooperative Producing Association.
<u>(1-55) - Change:</u>	Operator change to Graridge Corp.
<u>(3-58) - Unit:</u>	Enter in NCQU; name change to NCQU 36-15, operated by Graridge Corp.
<u>(5-65) - Change:</u>	Operator change to Petroleum Corp. of Texas.
<u>(5-66) - Change:</u>	Operator change to American Petrofina Co. of Texas.
<u>(4-69) - Propose P&A:</u>	Propose to plug by cutting and pulling 5-1/2".
<u>(6-69) - P&A:</u>	Set CIBP at 2933' and cap w/20' cmt. Circulate mud and spot 10 sx at 100'-surface. Set P&A marker.

. .

-

.

.

.

Celero Energy II LP API 30-005-00688 660 FSL & 1980 FEL Unit O, Section 36, T-12S, R-32E Chaves County, N. Mexico

Procedure to re-enter plugged well and return to production.

- 1. Blade off a 200'-by-200' location as shown on the attached location diagram.
- Dig out well head and install cellar. Dress off casing stubs and install risers for 8-5/8" and 5-1/2" casing. Install 8-5/8"-by-5-1/2", minimum 2000 psi WP, SOW, Larkin-style casing head with two outlets. Install minimum 2000 psi WP Larkin-style casing head on 5-1/5" casing.
- 3. RU pulling unit. Install manually-operated, dual-ram (blinds on bottom) 3000 psi WP BOPE and test to 1000 psi. RU tubing swivel and reverse unit pump taking returns off 5-1/2" casing head outlet with single line to return tank. Open and monitor the 5-1/2"-by-8-5/8" outlet for returns during drill out.
- 4. RIH with 4-3/4" bit, bit sub, (6) 2-3/8" regular DC's(3-1/8" OD) on 2-7/8", 6.5#, J-55, 8rd EUE workstring. Drill out cement from surface to 80' and pressure test to 500 psi (discuss w/office before proceeding). Continue drilling out surface plug, tag next plug at 2913', and pressure test to 500 psi (discuss w/office before proceeding). Drill out cement/CIBP at 2913'-2933'. Continue drilling out and clean out to original PBD of 3055'. Circulate hole clean using produced water from the Rock Queen Unit 10-ppg water tank. POOH standing back workstring.
- 5. RU wireline unit and run a casing inspection log from 2980' to surface. Run a GR/CCL/CBL from 2980' to T-O-C. Discuss results with office before proceeding. Run a GR/CCL/CNL from TD to 2000'.
- 6. RIH with retrievable treating packer and acidize the existing open hole with 1500 gals inhibited 7-1/2% NEFE HCL containing 10% toulene at maximum rate without exceeding 4000 psi surface treating pressure. Pump 10 gals gelled 10-ppg brine water containing 750# of graded rock salt after the first 750 gals of acid/toluene mixture. Flush with tubing volume plus 20 bbls of freshwater. Record initial, 15-minute, and 30-minute shut-in pressures.
- Swab back load recording initial and final fluid levels. TOOH w/treating packer LD workstring. RIH with 2-3/8", 4.7#, J-55, 8rd EUE production tubing and tubing anchor. Run pump and rods and a pump unit capable of lifting 200 BPD. Shut well in waiting on electricity and completion of tank battery.