Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office District 1 – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N French Dr , Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-03790
District III – (505) 334-6178	Santa Fe, NM 87505	5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM OCT	Danta 1 4, 1 11.1 0 / 5 0 0	6. State Off & Gas Lease No.
87505		
	CANDREPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
PROPOSALS.)	TION FOR PERMIT" (FORM C-101) FOR SUCH	Lovington San Andres Unit
	s Well 🛛 Other Water Injection	8. Well Number: 3
2. Name of Operator		9. OGRID Number: 24133
Chevron Midcontinent, L.P.		
3. Address of Operator		10. Pool name or Wildcat
15 Smith Road Midland, TX 79705		Lovington Graybrg San Andres
4. Well Location		
Unit Letter C: 6	60 feet from the North line and 1980	feet from theWestline
Section 36	Township 16-S Range 36-E	NMPM County Lea
	1. Elevation (Show whether DR, RKB, RT, GR, etc.,	
3843' GL		
Approved 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
Ciability in for plus		
Approved for plugging of well bore only. C-103 (Specifically for Subsequent Report of Downhous State nm us/ocd OTHER: Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB OTHER:		
Upg (Specifically for retained Day ABANDON REMEDIAL WORK ALTERING CASING		
under forms www emnrd state nm us/ocd web page		
CASING/CEMENT JOB		
DOWNHULL State nm us/ocd State no Us/ocd State no Us/ocd		
ds/ocd	web page	
13. Describe proposed or complete y state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE 7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
9/25/12 – Sqz 50 sx under pkr @ 4600'.		
7/25/12 Oq2 50 SK under pki & 1000 .		
9/26/12 – Set CIBP @ 4500'.		
9/27/12 - Spot 25 sx @ 4488', spot 30 sx @ 3069', TOC, tag @ 2755'. Perf @ 2195', spot 30 sx @ 2253'.		
9/28/12 – Tag plug @ 1938', perf @ 300', pump 50 sx to surface.		
Spud Date:	Rig Release Date:	
•		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE /	TITLE Representative	DATE <u>10/10/12</u>
	<i>-</i>	
Type or print name Matthew Brew	<u>ver</u> E-mail address: <u>mbrewer01@k</u>	eyenergy.com_ PHONE: <u>432-523-5155</u>
For State Use Only		
ADDROVED BY	THE NAME OF MAN	DATE 10-10-2012
Conditions of Approval (if any):	•	