

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

COPY

New Mexico Oil Conservation Division, District I

FORM APPROVED  
OMB No. 1004-0137  
Expires October 31, 2014

1645 N 4th Drive

Hobbs, NM 88240

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		7. If Unit of CA/Agreement, Name and/or No.
2. Name of Operator Celero Energy II, LP		8. Well Name and No. Rock Queen Unit #32
3a. Address 400 W. Illinois, Ste. 1601 Midland TX 79701	3b. Phone No. (include area code) (432)686-1883	9. API Well No. 30-005-00888
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 27, Unit I, T13S, R31E 1980' FSL & 660' FEL		10. Field and Pool or Exploratory Area Caprock; Queen
		11. County or Parish, State Chaves, NM

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Extend TA status
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

9/26/12 - Ran MIT. Test 30 mins to 515#. Held ok. Original chart is attached. OCD was notified for test. Celero would like to extend the TA status on this well.

HOBBS OCD

OCT 11 2012

RECEIVED

APPROVED FOR 12 MONTH PERIOD  
ENDING SEP 26 2013

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Lisa Hunt	Title Regulatory Analyst
Signature <i>Lisa Hunt</i>	Date 09/26/2012

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by <b>/S/ DAVID R. GLASS</b>	PETROLEUM ENGINEER	Date OCT 02 2012
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	File	Office ROSWELL FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

OCT 15 2012

