Form 3160-5 (August 2007)	UNITED STATES DEPARTMENT OF THE INTERIOF BUREAU OF LAND MANAGEMENT			OCD Hobbs		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010		
SUNDRY NOTICES AND REPORTS ON WE				ELLS		5. Lease Serial No NMNM01135		
	Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						6 If Indian, Allottee or Tribe Name	
<u>-</u> <u>-</u>	SUBMIT IN TRI		7 If Unit or CA/Agreement, Name and/or No					
1 Type of Well Oil Well	ner		8 Well Name and No FECTA 33 FEDERAL		RAL 2H			
2 Name of Ope OCCIDEN		DUARTE		9. API Well No. 30-025-40280-00-X1				
3a. Address			3b Phone No (include area code) Ph: 713,513 6640			10 Field and Pool, or Exploratory LUSK		
	HOUSTON, TX 77210 4 Location of Well (Footage, Sec., T, R, M, or Survey Description					11. County or Parish, and State		
Sec 33 T19S R32E NENW 141FNL 2347FWL						LEA COUNTY, NM		
	12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATI	E NATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF	SUBMISSION	TYPE OF ACTION						
Notice of	Intent	□ Acidize □ Alter Casing		epen cture, Treat		ion (Start/Resume) ation	□ Water Shut-Off □ Well Integrity	
□ ^{Subseque}	ent Report	Casing Repair		w Construction			□ ^{Other}	
🗖 ^{Final} Aba	Final Abandonment Notice					orarily Abandon Disposal		
13 Describe Prot	nosed or Completed On	Convert to Injection eration (clearly state all pertine	_				vimate duration thereof	
testing has be determined th	en completed. Final Al hat the site is ready for f	l operations. If the operation re bandonment Notices shall be fil inal inspection) D DETAILED DESCRIPT	led only after all	requirements, inclu	iding reclamatio	new interval, a Form 316 n, have been completed,	and the operator has	
-	to provide a copy Frac Job report -					DPROVED	₩\	
• •	pressures etc to				$\int r$	2 20°		
	••		ì		8	e' NOV	NAGENIENT	
14. Thereby cert	tify that the foregoing is	true and correct Electronic Submission # For OCCIDE		d by the BLM W		AUREAU SBAD FIEL	10:	
	Commit	For OCCIDE ted to AFMSS for processi	INTAL PERMI	AN LP, sent to the DEN TOPHER WALLS	he Hobbs on 11/02/201	2 143 CRW0031SE)		
Name (Printed	d/Typed) TAYLOR			v v	S ENGINEER			
Signature	(Electronic S	Submission)		Date 10/30/2	2012		•	
		THIS SPACE FO	DR FEDERA	L OR STATE	OFFICE U	SE		
Approved By	DWARD FERNAN	DEZ	TitlePETROLI	TitlePETROLEUM ENGINEER Date 11/02/20				
certify that the app	roval, if any, are attache plicant bolds legal or equ e the applicant to condu	d Approval of this notice does utable title to those rights in the action erations therein	Office Hobbs					
Title 18 U S.C See States any false,	ction 1001 and Title 43 fictitious or fraudulent	USC. Section 1212, make it a statements or representations as	a crime for any p s to any matter v	erson knowingly ar	nd willfully to m	ake to any department or	agency of the United	
	** BLM RFV	ISED ** BLM REVISEI	D ** BLM R	EVISED ** BI) ** BLM REVISE) **	

-

NOV	0	۲ _۲	2012
-----	---	----------------	------

OCCIDENTAL PERMIAN LTD respectfully requests to complete the Fecta 33 Federal 2-H as outlined below. DV-Tool remediation has been completed and CBL-VDL has been submitted for review. A notice of intent has been requested to review the plan forward for this well's completion. Additional safety factors have been considered and included in this proposed plan to provide reasonable assurance that well stimulation activities are conducted as designed, and stimulation fluids are going to the formation for which they were intended.

OBJECTIVE: After prior approval of CBL-VDL by BLM, if required, pressure test casing as per BLM requirements. Proceed to stimulate and complete horizontal Second Bone Spring well in 6 stages w/ 4 entry points per stage. Frac method will be Plug & Perf.

JOB NOTES ON EXECUTION:

•

- Operator will continuously monitor and record the pressure(s) during the well stimulation operations
 - Pressure will be contained in the string through which the stimulation is being pumped (5-1/2", 17#, L-80 casing)
 - o Annulus pressure will be monitored throughout job
 - If during the stimulation operation the annulus pressure increases by more than 500 psi over the annulus pressure immediately preceding the stimulation, the job will be shut-down and the BLM notified as soon as possible
 - Anticipated Treating Rate: 68-72 BPM
- Anticipated WHTP: 4500 psi (based on offset: Oxy Fecta 33 Federal 1-H)
- Anticipated Maximum Pressure: 5800 psi (based on offset: Oxy Fecta 33 Federal 1-H)
 - If during the stimulation operation, the WHTP should exceed 5800 psi, all pumps will be shut-down so as not to apply greater than 6192 psi on the casing (or no greater than 80% of burst at ANY TIME) and will move on to the next stage.
- Treat via: 5-1/2", 17#, L-80 casing (7740 psi Internal Yield Pressure)

PROPOSED OPERATIONS:

- 1. Clear location.
- 2. MIRU 2" Coiled Tubing Unit RIH & tag PBTD (CIBP @ 13,688', float collar @ ± 13,709') Report tag depth.
- 3. If required, pressure test casing as per BLM regulations.

NOTE: (BLM REGS FOR CASING TESTS: 0.22 PSI/ FT OF DEPTH W/ MINIMUM OF 1500 PSI NOT TO EXCEED 70% OF BURST - PRESSURE LOSS GREATER THAN 10% IN 30 MINUTES REQUIRES CORRECTIVE ACTION).

- PU TCP guns on 2" CT & TIH to perforate the toe fire guns hydraulically. Guns are 3.125" SDP-3375-311NT, 21.5 gm chg, 0.39" EHD, and 35.6" penetration w/ 6 JSPF on 60 degree phasing. Perforate first stage as per design w/ 38 holes. POOH w/ CT. RDMO CT Unit.
- 5. Set and load frac tanks.
- 6. RU Frac Unit & WL. Frac stage 1 down casing as per service company frac procedure.
 - Proposed Stage Volumes
 - o 3,000 gals 15% HCI Acid
 - o 200,000 gals gel
 - 6. 200,000 lbs of 20/40 CRC proppant
 - Proposed Total Job Volumes (6 stages)
 - o 18,000 gats 15% HCI Acid
 - o 1,200,000 gals gel
 - o 1,200,000 lbs 20/40 CRC proppant
- 7. RU WLU and set CBP between stages. Perf the next stage as per design w/ 3.125" Titan EXP-3319-322T charge, 0.39" EHD, and 40.56" penetration w/ 6 JSPF on 60 degree phasing, 38 holes total. We will pump down plugs & guns. Guns are 3.125" Titan EXP-3319-322T charge, 0.39" EHD, and 40.56" penetration w/ 6 JSPF on 60 degree phasing. Plugs are Magnum Rapid Mill 10K Composite Ball Drop Plugs. An Owen, or Titan "Shorty Compact" setting tool will be required.
- 8. RD WLU. RU Frac Unit. Frac stage 2 down casing as per service company frac procedure.
- 9. Repeat steps for stages 3-6.
- 10. Shut-in well overnight and RD Frac equipment and WLU.

