New Mexico Oil Conservation Division, District I 1625 N. French Drive

Form 3160-5 (April 2004)

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

UNITED STATES Hobbs, NM	88249	•
DEPARTMENT OF THE INTERIOR		
RUREAU OF LAND MANAGEMENT	٠.	

5. Lease Serial No. LC-030180A

abandoned w		ON MELLS		
SUBMIT IN TR	his form for proposals to drill or rell. Use Form 3160-3 (APD) for	or to re-enter such proposa	aii	If Indian, Allottee or Tribe Name
	IPLICATE- Other instructions	on reverse si	de. 7. I	f Unit or CA/Agreement, Name and/or No.
. Type of Well X Oil Well	Gas Well Other	· ·	8. 1	Well Name and No.
2. Name of Operator South	west Royalties, Inc.			rnsworth A Fed #4 API Well No.
a Address 6 Desta Dr		c No. (include area o		0-025-12 00x 3
Midland, T)686-9927		Field and Pool, or Exploratory Area
Location of Well (Footage, Sec.,				arborough Yates 7 Rive
1960' FNL & 660'	FWL, Sec 18, T26S, R3	7E, Spot E		County or Parish, State ea County, NM
12. CHECK A	PPROPRIATE BOX(ES) TO INDICAT	TE NATURE OF	NOTICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF	ACTION	
Notice of Intent	Acidize Deeper		Production (Start/Rest Reclamation	ume) Water Shut-Off Wett Integrity
Subsequent Report			Recomplete	Other
Final Abandonment Notice	☐ Change Plans ☐ Plug ar		Cemporarily Abandon Water Disposal	
4/6/05 Cut and pu 4/7/05 Spot 40 sx 4/7/05 Respot 25 4/7/05 Respot 25 4/8/05 Spot 30 sx 4/8/05 Spot 30 sx 4/8/05 Perf 9-5/8 displace 1	from 2700' - 2520'. 11 7" csg. from 1450' c. cmt. from 1506' - 1 sx. cmt. from 1446' sx. cmt. from 1446' - c. cmt. from 1190' - 1 c. cmt. from 560' - 43 comt. from 560', set 9-5 coc down to 60', WOC to	370', WOC - 1369', W 1369', WO 066'. 6', WOC & /8" pkr. @ o test.	OC & tag TOC & tag TOC durface,	OC @ 1446'. C @ 1349'. 443'. sqz. w/ 50 sx. emt.,
WOX to pr	essure test, sqz. wou essure test.	ld not pre	ssure test	, resqz w/ 50 sx. cmt
14. I hereby certify that the for	egoing is true and correct	1	Derw	m How 1/5/6-
Name (Printed/Typed)	• •	Title	Agent	
Name (Printed/Typed)				<u></u>
Name (Printed/Typed)	my	Date 4/	18/05	
Name (Printed Typed) Roger Massey	THIS SPACE FOR FEDER	<u>.l. 4/</u>	18/05	

(Instructions on page 2)

GWW

Approved as to plugging of the well born trability under bond is retained until surface restoration is completed.

Form 3160-5 (April 2004)

1. Type of Well

2. 3a Öil Well

UNITED STATES DEPARTMENT OF THE INTERIOR BURGALLOG LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Other

Gas Well

FORM APPROVED	
OM BNo 1004-0137	
Expires March 31, 2007	7

_			
5.	Lease Serial	No.	

6.	If Indian, Allottee or Tribe Name
7.	If Unit or CA/Agreement, Name and/or No.
\mathbf{I}	1 4 to 1
8	Well Name and No

Farnsworth A Fed #4

11. County or Parish, State

Name of Opera	Southwest Royalties,	Inc.	9. API Well No.
Address	•	3b. Phone No. (include area code)	30 025- /200

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, REPORT, O	R OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Wetl Integrity Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Continued

4/12/05 Tag TOC @ 60', pressure test @ 500#, small leak off 100# in 5 minutes.
4/12/05 Perf well @ 45', mix & sqz. 35 sx. cmt. to circulate cement to surface up 9-5/8" x 13", WOC.

4/13/05 Tag TOC @ 10', top fill 9-5/8" w/ 20 sx. cmt.

4/13/05 RDMO. Cut off wellhead & anchors, install dry hole marker, and clean location.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Roger Massey	Title Agent		
Signature Size of Many	Date 4/18/05		
THIS SPACE FOR FEDER	AL OR STATE OFFICE USE		
Approved by SERG SGD.) DAVID R. GLASS		Date	MAY 0 3 2005
Conditions of exporate, if any, are attached. Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subjection.	susuit or		 ,

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, definious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW

Approved as to plugging of the well bore trability under bond is retained until writer restoration is completed.