· · · · · · · · · · · · · · · · · · ·	
Submit 3 Copies To Appropriate District State of New Mexico Energy, Minerals and Natural Re	Form C-103 March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II OIL CONSERVATION DI	VISION <u>30-025-35510</u>
1301 W. Grand Ave., Artesia, NM 88210 District III	Dr. 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	STATE FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOF PROPOSALS.)	
1. Type of Well: Oil Well Gas Well X Other	8. Well Number
2. Name of Operator	9. OGRID Number
Nearburg Producing Company	015742
3. Address of Operator	10. Pool name or Wildcat Wolfcamp
3300 N A St., Bldg 2, Ste 120, Midland, TX 79705	Ssudo;Morrow,-West-
4. Well Location	
Unit Letter <u>KN</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line	
Section 35 Township 20S Range 35E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3688'	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit location: UL Sect Twp Rng Pit type Depth Distance from nearest surface water Below-grade Tank Location UL	
feet from the line and feet from the	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REM	EDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS CON	IMENCE DRILLING OPNS. PLUG AND ABANDONMENT
	ING TEST AND
OTHER: OTH	ER: Plug back f/ Morrow t/ Wolfcamp
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
Mull 18 ¹⁵²⁰ 27	
Per phone message from Donna Maul, OCD rep, on 5/13/05, please find attached the work that was performed on the subject well to move from the Morrow formation to the Wolfcamp.	
on the subject were to move from the morrow formation to the worrcamp.	
	(10112) 22/2010 22/2010
	$\langle P \rangle = \langle P \rangle \langle P \rangle$
	C. Au
	E Company and the company and
I hereby certify that the information above is true and complete to the best of grade tank has been/will be constructed or closed according to NMOCD guidelines	If my knowledge and belief. I further certify that any pit or below-
SIGNATURE	<u>Production Analyst</u> <u>DATE</u> <u>5/15/05</u> dress: sjordan@nearburg.com
Type or print name Sarah Jordan	Telephone No. 432/686-8235
(This space for State use)	PETPOLE 4 2005
APPROVED BY	PETROLEUM ENGINEER DATE MAY 2 4 2005
Conditions of approval, if any:	
2A 85	udo Morrow West

Nearburg Producing Company

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Simms 35 State #3 660' FSL and 1980' FWL, Section 35, T20S, R35E Morrow Lea County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

- 02/15/05 MIRU pulling unit. SITP 400#. Blew dn quickly to tank. ND wellhead. NU BOP. MIRU pump truck. Load tbg w/44 bbls 2% KCL wtr. Release pkr. RDMO pump truck. POOH w/tbg & pkr. Sent pkr to shop for repairs. SDFN. Current Operation This AM: Set CIBP.
- 02/16/05 Road crew to location. MIRU JSI. RIH w/gauge ring/JB/GR/CCL to 13,310'. PU & log from 11,700' to 10,600'. POOH. RIH w/5 1/2" CIBP & set @ 13,130', isolating Morrow perfs from 13,174'-13,308'. POOH. Made 2 dump bailer runs & dump 35' cmt on top of CIBP. New PBTD @ 13,095'.RDMO JSI. RIH w/1 2 3/8" SSN w/1.79" ID, 376 jts 2 3/8" L80 4.7# EUE 8rd tbg. SN @ 11,900'. SI & SDFN. Current Operation This AM: Circ completion fluid and swab.
- 02/17/05 Road crew to location. Circ hole w/280 bbls 2% KCL wtr loaded w/0.5 gpt BJ Clay Master 5C & pkr fluid. Test to 2,000#. OK. RIH w/swab. IFL @surface. Made 12 runs & rec'd 60 bbls wtr. FFL @ 2,700'. RD swab. POOH w/tbg. SI & SDFN. Current Operation This AM: Perf.
- 02/18/05 Road crew to location. MIRU JSI. RIH w/1 3 3/8" expendable perf gun/CCL loaded w/4 JSPF, 22.7 gram charges, .43" entry hole, 29.56" penetration. Correlate on depth. Perforate from 11,602'-11,626' w/4 JSPF, 96 holes. POOH. No chg in FL. RDMO JSI. MIRU Hydrostatic tbg testers. Hydrostatically TIH to 7,000# above slips w/1 2 3/8" x 6' N80 tbg sub w/RA bead & re-entry guide, 1 2 3/8" x 5 1/2" 17-20# PLS 10K pkr w/50K shear, 1 2 3/8" x 5 1/2" XL O/O tool w/Baker 1.81" F frac hardened profile nipple, 363 jts 2 3/8" L80 4.7# EUE 8rd tbg. RDMO tbg testers. Set pkr in 15K compression @11,499' using 20' KB, re-entry guide @ 11,510'. ND BOP. NU 2 3/8" x 5K tree. Load annulus w/49 bbls 2% KCL wtr, test to 2,000#. OK. RIH w/swab IFL @ 2,700'. Made 4 runs & rec'd 20 bbls wtr w/no show of oil. FFL @ 5,500'. Left open to tank on 20/64" choke. SDFN. Current Operation This AM: Swab.
- 02/19/05 Road crew to location. Tbg open to tank on 20/64" choke w/light gas blow. RIH w/swab. IFL @ 4,500'. Made 11 runs w/10-15% oil cut on each run & dried up. Rec'd 26 bbls wtr & 10 bbls oil. Light gas blow on tbg. SD 1 hr. RIH w/swab. Had 200-300' of fluid entry. Rec'd trace of oil. Left open to tank on 20/64" choke w/light gas blow. Have rec'd 46 bbls wtr & 10 bbls oil in 2 days. SDFW. Will acidize on Monday A.M. Current Operation This AM: Acidize.
- 02/21/05 Road crew to location. Tbg open to tank on 20/64" choke w/light gas blow. RIH w/swab. IFL @ 7,500'. Made 3 runs w/60-70% oil cut on 1st run & 10-20% oil cut on last 2 runs. Rec'd 11 bbls wtr & 4 bbls oil. MIRU BJ Services & Guardian tree saver. Conduct safety meeting. Test lines to 8,000#. Treat Wolfcamp perfs from 11,602'-11,626' via 2 3/8" L80 4.7# tbg w/4,000 gals (96 bbls) 15% HCL acid, dropping 100 7/8" ball sealers in clusters of 25 thru acid volume. Tbg loaded w/36 bbls acid pumped, broke @ 4,276#. Pressure climbing after 1st set of balls on, saw slight ball action w/remaining ball sealers. Flushed w/48 bbls 2% KCL wtr. Pumped job @ avg rate of 3.5 bpm w/avg press of 5,807#, max 6,551#, min 4,276#. SD. ISDP 5,230#, 5 min 5,092#,10 min 5,009#, 15 min 4,969#. Held 1,500# on annulus during job. RDMO BJ Services & tree saver. Have 144 bbls load to recover. Started flow back approx. 1 hr after SD w/4,500# TP. Flowed back 48 bbls wtr, 15-20 bbls acid & started recovering oil. Flowing oil & gas to frac tank on 12/64" choke w/800# FTP @ rate of 15-20 bbls/hr. Left open to frac tank w/well tester on location. Current Operation This AM: RDMO if well still flowing.

Nearburg Producing Company

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Simms 35 State #3 660' FSL and 1980' FWL, Section 35, T20S, R35E Morrow Lea County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

- 02/22/05 Road crew to location. Tbg open to frac tank on 48/64" choke w/20-40# FTP, flowing back oil & gas w/some wtr @ rate of 3-5 bbls/hr. Flowed back 150bbls oil & 8 bbls wtr overnight. Have rec'd 104 bbls of load. Have 40 bbls load left to recover. RDMO pulling unit. Left open to frac tank on 48/64" choke. Final Report. Current Operation This AM: Left open to frac tank.
- MIRU swab unit. Tbg open to frac tank w/no press or gas blow. RIH w/swab. IFL @
 7,000'. Made 13 runs w/F.L. coming up hole, rec'd 30 bbls oil, well started flowing. Flowed back 15 bbls oil in 1 1/2 hrs. Well stopped flowing. Made 10 additional swab runs w/strong gas blow after each run, F.L. scattered on each run, pulled from 9,000' on each run (SN @ 11,497'). Rec'd 20 more bbls oil. Rec'd 66 bbls oil & 1/2 bbl wtr total. Tbg gassing to frac tank on 30/64" choke. Left open to frac tank on 30/64" choke. Current Operation This AM: Swab.
- 03/01/05 Road crew to location. Tbg open to frac tank on 30/64" choke w/light gas blow. Flowed 20 bbls oil overnight. RIH w/swab. IFL @ 5,500'. Made 12 runs& rec'd 29 bbls oil. Well flowing. Flowed 12 bbls oil in 2 hrs. Left open to frac tank on 30/64" choke w/gas blow & intermittent fluid flow. RDMO swab unit. Have rec'd 127 bbls in 2 days. Sent to production. Final Report.

Current Operation This AM: Sent to production.

- 03/04/05 Road rig & crew to location from Grama Ridge East 34 State #1. Spot rig on location. Will MIRU Mesa pulling unit on Monday AM and POOH w/ pkr then RIH w/ TAC & SN to put well on rods. SDFW. Perfs @ 11,602'- 11,626'. PBTD @ 13,095' (CIBP). Current Operation This AM: Release pkr and POH w/ tbg.
- MIRU Mesa Well Service pulling unit. Tbg was open to frac tank with no pressure. Blew csg pressure dn to frac tank. NU BOP. Tried to release pkr. Had to unlatch from O/O to equalize fluid. Latch back up to On/Off. Release 2 3/8" x 5 1/2" 17-20# PLS pkr w/ 50K shear. POOH w/ 363 jts- 2 3/8"L-80 4.7# EUE 8rd tbg, 2 3/8" x 5 1/2" XL O/O tool w/ 1.81" Baker "F" frac hardened nipple, 2 3/8" x 5 1/2" PLS pkr, 2 3/8" x 6' N-80 4.7# EUE8rd tbg sub w/ RA bead & re-entry guide. Pulling unit had tong hose break while POOH w/ tbg. Waited for hose for 1hr. RIH w/ 1 jt- 2 3/8" L-80 4.7# EUE 8rd tbg, 2 3/8" x 5 1/2" TAC w/ 45,000# SN w/ 1.78" ID, 5 jts- 2 3/8" L-80 4.7# EUE 8rd tbg. Put TIW valve in tbg. Close BOP rams. SDFN. Will ND BOP & set TAC in the AM. Had Coombes Trucking bring 6' x 20' heater treater from Permian Tank in Odessa & unload on location. Will set in the AM. Two-State hauled all the rods from the Grama Ridge East 34 State #1 to location. Perfs @ 11,602'-11,626'. PBFD @ 13,095' (CIBP).

Current Operation This AM: TIH w/ pump and rods.

03/08/05 Remove TIW valve from tbg. Blow csg dn. Open BOP rams. ND BOP. Tried to set TAC, but could not get to hold. POOH w/ 364 jts- 2 3/8" L-80 4.7#EUE 8rd tbg. LD 2 3/8" x 5 1/2" TAC (locked up- wouldn't turn). PU & RIH w/ another 2 3/8" x 5 1/2" TAC w/ 45,000# shear, 364 jts- 2 3/8" L-804.7# EUE 8rd tbg. ND BOP. Set TAC in 12,000# tension. NU WH. Had Banta roustabout gang build wellhead and work on hooking up new 6' x 20'heater treater. Had Coombes Trucking set heater. Had TRM put 30 Bbls fresh wtr in heater to hold dn. Had Banta tandem axel truck move Lufkin 912pumping unit to location & set. Glenn's moved the generator to location & Eddins Walcher brought the diesel fuel. Will have Dean's electric bring electric panel & set in the AM. Put TIW valve in pumping tee. Will RIH w/ pump & rods in the AM. SDFN. Perfs @ 11602'- 11,626'. PBTD @ 13095' (CIBP). Current Operation This AM: Finish RIH w/ pump and rods.

Nearburg Producing Company

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Simms 35 State #3 660' FSL and 1980' FWL, Section 35, T20S, R35E Morrow Lea County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

03/09/05 Banta roustabouts finished building wellhead & hooking up to flowline. Remove TIW valve from pumping tee. PU & RIH w/ rebuilt 2" x 1 1/4" x 24'RHBC pump w/ HW SCID Bbl (.001"), 1 1/4" x 3' PA plunger (.006"), DV T/C b&s, 232" stroke w/ 1" x 1' LS & SRG & 1" x 6" strainer nipple,(12) 1 1/2" x 25' Grade K Sinker bars w/ 3/4" pins, (61) 3/4" x 25' T-66 rods w/ FHTC (from yard), (228) 3/4" x 25' T-66 rods w/ FHTC (from Grama Ridge), (22) new 3/4" x 25' T-66 rods w/ FHTC, (5) 7/8" x 25' T-66 rods w/ SHTC (from yard), (15) new 7/8" x 25' T-66 rods w/ SHTC,(119) 7/8" x 25' T-66 rods w/ SHTC (from Grama Ridge 34 #1), (2) new 7/8" x 6' x 8' T-66 pony rod subs, 1 1/4" x 26' PR w/ 1 1/2" x 16' PRL. Hang well on. Space pump 36" off bottom. RU Key pump truck to load & test tbg w/ 27 Bbls 2% KCL wtr. Tested tbg to 500#. Held O.K. Good pump action. Banta gang had heater treater plumbed in good enough to turn production into it. They will complete hookup on burner in the AM. RDMO Key pump truck & Mesa pulling unit. Clean location. The pumping unit was stroking 9 SPM and we need unit to stroke 6 SPM. Left well down overnight & will resheave unit to stroke 6 SPM in the AM and start unit then. Perfs @ 11602'- 11626'. PBTD @ 13095' (CIBP w/ 35' cmt). FINAL REPORT.

Current Operation This AM: Start pumping unit.

