

Submitt 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-21662
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-5310
7. Lease Name or Unit Agreement Name State CD
8. Well Number 2
9. OGRID Number 013837
10. Pool name or Wildcat Corbin Abo

Pit or Below-grade Tank Application ☒ or Closure ☐  
Pit type Plugging Depth Groundwater 150' Distance from nearest fresh water well 1000' Distance from nearest surface water 1000'  
Pit Liner Thickness: 12 mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator Mack Energy Corporation
3. Address of Operator P. O. Box 960 Artesia, NM 88211-0960
4. Well Location Unit Letter <u>B</u> <u>990</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>32</u> Township <u>17S</u> Range <u>33E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4064' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: \_\_\_\_\_ ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: \_\_\_\_\_ ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set CIBP @ 5972' w/35' cement cap above perfs at 6072' and circ hole with mud.
3. Perf @ 2949 squeeze 50' above and below 8 5/8" shoe. WOC and tag.
4. Perf @ 1250' squeeze 35 sx @ 1250', 50' above top of salt.
5. Perf @ 344' squeeze 50' above and below 13 3/8" casing shoe. WOC and tag.
6. Set 10 sx surface plug.
7. Install dry hole marker.



THE OIL CONSERVATION DIVISION MUST  
BE NOTIFIED 24 HOURS PRIOR TO THE  
BEGINNING OF PLUGGING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 5/23/2005  
Type or print name Jerry W. Sherrell E-mail address: jerrys@mackenergycorp.com Telephone No. (505)748-1288  
For State Use Only

APPROVED BY: Gary W. Wink ORIGINAL SIGNED BY GARY W. WINK DATE \_\_\_\_\_  
Conditions of Approval (if any): \_\_\_\_\_ OC FIELD REPRESENTATIVE/STATE MANAGER  
MAY 31 2005

MACK ENERGY CORPORATION  
STATE CD #2  
Sec 32 T17S R33E 990FNL 1980FEL

