State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATIO	N DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr., Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025	-29129
DISTRICT II	ŕ		5. Indicate Type of Lease	FEE
1301 W. Grand Ave, Artesia, NM 88210	NM 88210		STATE X 6. State Oil & Gas Lease No.	TEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		NORTH HOBBS (G/SA) UNIT Section 24		
1. Type of Well:			8. Well No. 212	
Oil Well Gas Well Other Injector				
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator 1017 W. Standlind Rd. HORRS, NM, 88240, 505/207, 8200			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 4. Well Location				
Unit Letter C : 1263	Feet From The NORTH	Feet	t From The WEST	Line -
Section 24	Township 18-S	Range 37-E	NMPM	LEA County
	11. Elevation (Show whether DF, RKB, RT C 3685' GL	GR, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	terial	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON REM	EDIAL WORK	X ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT			
PULL OR ALTER CASING	Multiple Completion CASI	NG TEST AND CEMEN	IT JOB	
OTHER:	ОТН	ER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
 RUPU. Pull Injection equipment. Perforate the following intervals; 4176-78 and 4205-06, using 2 spf, 120 deg ph. (10 holes). 				
4. RIH w/4.5" Guiberson UNI VI pc pkr, XL on/off tool w/1.875 ss "F" nipple, 132 jts 2-7/8" Duoline tbg. Pkr (@4145)				
5. Load csg w/150 bbl pkr fluid. Tst csg to 540 psi for 30 min and chart for the NMOCD. 6. RDPU. Clean Location.				
o. RDI o. Cican Location.			228	4 2
Rig Up Date: 05/16/2005 Rig Down Date: 05/19/2005			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	·
rag Bown Bate. 65/17/2005			12223	20261811
	true and complete to the best of my knowledge ar	nd belief. I further certify	that any pit or below-grade tank h	as been/will be
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved				
POT 9.111 + plan				
SIGNATURE Robert	illert TIT		pletion Specialist DATE	
TYPE OR PRINT NAME Robert Gill	pert E-mail address: rob	ert_gilbert@oxy.com	TELEPHONE NO.	505/397-8206
APPROVED BY LAW WILLIAM OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE				
CONDITIONS OF APPROVAL IF ANY:	Clerk OC FIELD	LEEPRESENTATIVE	E II/STAFF MANAGES DAT	TE

