District Cash French Dr., Hobbs, NM 82240 District III 120 South St. Francis Dr. Santa Fe, NM 87505 Sant
1301 W. Grand Ave., Arteis, NM 88210 1220 South St. Francis Dr. Santa Fe, NM 87505 S. Indicate Type of Lease STATE FEE
1220 South St. Francis Dr. STATE FEE FEE
Sunday Notice Sunday Fe, NM State Sunday Fe, NM State Sunday Fe, NM State Sunday Fe, NM Sunday Notice Sunday Fe, NM Sund
SUNDRY NOTICES AND REPORTS ON WELLS (ON ONT USE THIS FORM ROB PROPOSALS TO DRILLO & RO DEPENDEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS). 1. Type of Well: Oil Well: Gas Well Other 2. Name of Operator
1. Type of Well: Oil Well Gas Well Other S. Well Number 10
Amerada Hess Corporator P.O. Box 840 Seminole, TX 79360 4. Well Location Unit Letter D : 330 feet from the North line and 660 feet from the West line Section 35 Township 19S Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3648' GL Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Pit type Depth to Groundwater Distance from nearest fresh water well Selection Of Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING CANING/CEMENT JOB OTHER: OTHER Knock out CIBP 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 5/15/2005 thru 5/22/2005 MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc. & acidized ABO perfs w/4500 gals 15% ABO blend acid fr/7260'-7370'. RD BJ Svc. Swabbed well. TiH w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
3. Address of Operator P.O. Box 840 Seminole, TX 79360 4. Well Location Unit Letter D : 330 feet from the North line and 660 feet from the West line Section 35 Township 19S Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3648' GL Pit or Below-grade Tank Application or Closure Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Unit Thickness: mil Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOB PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: OTHER: Knock out CIBP 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 5/15/2005 thru 5/22/2005 MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc & acidized ABO perfs w/4500 gals 15% ABO blend acid fir/7260-7370'. RD BJ Svc. Swabbed well. Tilh w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
4. Well Location Unit Letter D: 330 feet from the North line and 660 feet from the West line Section 35 Township 19S Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3648' GL Pit or Below-grade Tank Application D: or Closure D Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water P Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUS AND ABANDON CHANGE PLUS AND ABANDON CASING/CEMENT JOB TEMPORARILY ABANDON HULTIPLE COMPL CASING/CEMENT JOB OTHER: OTHER: Knock out CIBP 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 5/15/2005 thru 5/22/2005 MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc & acidized ABO perfs w/4500 gals 15% ABO blend acid fr/7260'-7370'. RD BJ Svc. Swabbed well. TilH w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
Unit Letter D : 330 feet from the North line and 660 feet from the West line Section 35 Township 198 Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3648' GL
Section 35 Township 19S Range 36E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3648' GL Pit or Below-grade Tank Application or Closure
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3648' GL
3646'GL
Pit type
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Subsequent Portion 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check Box 2. Check
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: Knock out CIBP MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc & acidized ABO perfs w/4500 gals 15% ABO blend acid fr/7260'-7370'. RD BJ Svc. Swabbed well. TIH w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: Knock out CIBP MULTIPLE COMPL CASING/CEMENT JOB MULTIPLE COMPL OTHER: Knock out CIBP MULTIPLE COMPL CASING/CEMENT JOB MULTIPLE COMPL OTHER: Knock out CIBP MULTIPLE COMPL CASING/CEMENT JOB MULTIPLE COMPL OTHER: Knock out CIBP MULTIPLE COMPL CASING/CEMENT JOB MULTIPLE COMPL OTHER: Knock out CIBP MULTIPLE COMPLETION: Attach wellbore diagram of proposed completion or recompletion. 5/15/2005 thru 5/22/2005 MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc & acidized ABO perfs w/4500 gals 15% ABO blend acid fr/7260'-7370'. RD BJ Svc. Swabbed well. TIH w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING ALTERING CASING CA
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 5/15/2005 thru 5/22/2005 MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc & acidized ABO perfs w/4500 gals 15% ABO blend acid fr/7260'-7370'. RD BJ Svc. Swabbed well. TIH w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 5/15/2005 thru 5/22/2005 MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc & acidized ABO perfs w/4500 gals 15% ABO blend acid fr/7260'-7370'. RD BJ Svc. Swabbed well. TIH w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
5/15/2005 thru 5/22/2005 MIRU Tyler Well Service and installed 6" 900 manual BOP. Tag CIBP @ 7210'. Drilled out CIBP @ 7210' and pushed down to 7430' (60' below bottom ABO perf). RU BJ Svc & acidized ABO perfs w/4500 gals 15% ABO blend acid fr/7260'-7370'. RD BJ Svc. Swabbed well. TIH w/sub eqpt. Hooked up well and began pumping. Well test on 6/6/2005: 88 BOPD, 1501 BWPD, 275 MCFPD.
87 89 1011 12 73 78 78 78 78 78 78 78 78 78 78 78 78 78
12.34 (et 81 (t) 9) (et 8) (et
12.34 See 1.19 See 1.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I sometime to the best of my knowledge and belief.
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.
SIGNATURE
Type or print name Carol J. Moore E-mail address: cmoore@hess.com Telephone No. (432)758-6738 For State Use Only
APPROVED BY: