## MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

## NEW MEXICO OCD HOBBS BID ID # 50-521-07-00442 CONTRACT # 05-521-0750-0234

OPERATOR: WALTER W. ANDERSON

Lease:

S.E. ANDERSON ESTATE # 1

Project:

P & A – CEMENTING REPORT

06-13-05 - SPOT 50 SXS @ 4200'-4090' & TAG

06-15-05 - PERFORATE @ 2211' -

06-15-05 - SPOT 60 SXS @ 2260'-2058' & TAG

06-15-05 - PERFORATE @ 475' & 433'

06-15-05 - SPOT 60 SXS @ 525'-378' & TAG

06-16-05 - PERFORATE 7" & 8 5/8" CASING @ 60'

06-16-05 - SQUEEZE 45 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER CIRCULATE 10# MUD

## MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

## NEW MEXICO OCD

Lease:

S.E. ANDERSON ESTATE

Well:

#1

SUPERVISOR - FRANK RIVAS

Operator:

WALTER W. ANDERSON P & A - API # 30-005-20488

Project: Contract:

05-521-0750-0234

IFB

50-521-07-00442

BID = \$ 18,992.00

06-09-05

(5 HRS)

MIRU - NDWH - NUBOP - POOH WITH 194 RODS - NUBOP - TUBING STUCK - CLOSE IN

6-10-05

(8 HRS)

WORK TUBING - TRY TO CIRCULATE LOOSE - PUMP 20 BBLS FRESH WATER - WELL ON VACUUM - WORK TUBING - CLOSE IN WELL

5 HRS RIG TIME @ \$ 175.00/

(work tubing)

...\$ 875.00

06-13-05 (12 HRS)

RUN GAUGE RING TO 4220' - CUT 2 3/8" TUBING @ 4200' - POOH W/135 JOINTS - RUN 7" GAUGE RING TO 4000' - RUN PACKER TO 4000' - PUMP 20 BBLS WATER DOWN TUBING -ATTEMPT TO LOAD BACKSIDE - TUBING BEGIN TO FLOW - POOH WITH PACKER - RIH OPEN-ENDED TO 4200' - SPOT 50 SXS CEMENT - POOH - CLOSE IN WELL

5 HRS RIG @ \$ 175.00/ (tubing cut, trip packer)

. . \$ 875.00

1 - TUBING CUT @ 4200'

..\$ 1,400.00

6-14-05 (12 HRS)

RUN TUBING & TAG @ 4090' - CIR. 10# MUD - POOH - NDWH - WELD ON PULL NIPPLE CUT CASING @ 2211' - NOT FREE - CUT CASING @ 475' - MOVE 8' - CUT CASING @ 433' -MOVE 4' - ATTEMPT TO CIRCULATE LOOSE - CIR. OUT 8 5/8" CASING - SHUT DOWN

4 HRS RIG @ \$ 175.00/ (tag plug with tubing-attempt to pull casing-weld on) WELDER (DISCOUNTED)

700.00

90.00

. . \$

3-CASING CUTS OFFSET BY 3 PERFS REQUIRED - CASING CUTS DISCOUNTED

6-15-05

(10 HRS)

CUT OFF PULL NIPPLE - RIH & SPOT 60 SXS @ 2260' - POOH - WOC - TAG @ 2058' - POOH & SPOT 60 SXS @ 525' - POOH

6-16-05

(11 HRS)

TAG @ 378' - PERFORATE 7" & 8 5/8" CASING @ 60' - FLANGE UP WELLHEAD SOUEEZE 45 SXS @ 60' TO SURFACE - LEAVING 7" CASING FULL - RIG DOWN - CUT OFF WELLHEAD & ANCHORS - INSTALL DRY HOLE MARKER - COVER PIT & CELLAR - MOVE OUT

1 EXTRA PERF @ 60'

. . \$ 400.00

CREDIT:

194 RODS @ \$ 2.00/ 4200' OF 2 3/8" TUBING @ \$ .20/FT 29 SXS CEMENT @ \$ 12.00/SACK

388.00

840.00 348.00

(BID 244 SXS- USED 215 SXS)

COST = \$21,635.00