

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-37250
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit
2. Name of Operator Occidental Permian Limited Partnership	8. Well Number 626
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294	9. OGRID Number 157984
4. Well Location SHL: Unit Letter K : 2320 feet from the South line and 2225 feet from the West line BHL: F 2614 North 2225 West Section 29 Township 18-S Range 38-E NMPM County Lea	10. Pool name or Wildcat Hobbs; Grayburg - San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3646' GR	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: Spud & Run Surface Casing ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 6/29/05

Type or print name Mark Stephens E-mail address: Mark\_Stephens@oxy.com Telephone No. (713) 366-5158

For State Use Only

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE \_\_\_\_\_

Conditions of Approval, if any:

JUL 11 2005

6/21/05: MI x RU. Spud 12-1/4" hole at 6:45 p.m. (NMOCD notified)

6/22/05 -

6/23/05: Run 37 jts. 8-5/8", 24#, J-55, ST&C casing with 10 centralizers and set at 1540'.  
RU Halliburton x cement with 450 sx. PBCZ lead and 300 sx. Premium Plus tail.  
Displace with 10 bbls FW x 85 bbls brine and circulate 104 sx. cement to surface.  
WOC 4 hrs. Cut off casing x weld on wellhead x NU BOP. Pressure test blind rams  
and casing to 1500 psi. Pressure test pipe rams, annular, and choke manifold to  
1500 psi. Drill out cement and resume drilling operations.

