State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVATION D	IVISION
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis I Santa Fe, NM 87505	Dr. WELL API NO.
DISTRICT II	,	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210		STATE X FEE
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NO	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BA	CK TO A NORTH HOBBS (G/SA) UNIT
DIFFERENT RESERVOIR. USE "A	PPLICATION FOR PERMIT" (Form C-101) for such pr	oposals.) Section 25
1. Type of Well: Oil Well X	Gas Well Other	8. Well No. 411
2. Name of Operator Occidental Permian Ltd.	/	9. OGRID No. 157984
3. Address of Operator		10. Pool name or Wildcat HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/397-8200	
4. Well Location		
Unit Letter <u>A</u> : <u>330</u>		330 Feet From The EAST Line
Section 25	Township 18-S R 11. Elevation (Show whether DF, RKB, RT GR, etc.	ange <u>37-E</u> NMPM <u>LEA</u> County
	3660' GR	,
Pit or Below-grade Tank Application	or Closure	
Pit Type Depth of Ground	Water Distance from nearest fresh w	vater well Distance from nearest surface water
Pit Liner Thickness mil	Below-Grade Tank: Volume bbls;	Construction Material
	k Appropriate Box to Indicate Nature of Notic	ce, Report, or Other Data
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL	WORK X ALTERING CASING
	CHANGE PLANS COMMENC	E DRILLING OPNS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	
OTHER:	OTHER:	
OTHER:       OTHER:         13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE       RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.         1. RUPU. Pull ESP equipment.       3         2. Stimulate perfs 4180-4244 w/2000 g 15% NEFE HCL acid.       3		
1. RUPU. Pull ESP equipment.		33 - Corros
3. RIH 2.25" tbg pump, 134 jts 2-7/		
<ol> <li>Respace pump. Load and tst tbg.</li> <li>RDPU. Clean Location.</li> </ol>	NU wellhead.	
3. RDFU: Clean Location.		<b>A2</b> 5262728
Rig Up Date: 07/05/2005		18 600 B
Rig Down Date: 07/07/2005		A
C		
		Sc150267.8/1
	true and complete to the best of my knowledge and belie	f. I further certify that any pit or below-grade tank has been/will be
constructed or closed according to NMOCD guidelines	, a general permit or an (atta	ached) alternative OCD-approved
DA 40	, a general permit	
SIGNATURE Kobul 4		Workover Completion Specialist DATE 07/14/2005
TYPE OR PRINT NAME Robert Gilb	ert E-mail address: robert_gill	bert@oxy.com TELEPHONE NO. 505/397-8206
APPROVED BY Harry W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER		
		DATE
CONDITIONS OF APPROVAL IF ANY:		JUL 2 0 2005