Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 ISON SERVATION DIVISION	<u>30-025-09394</u> 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: STATE A A/C 1
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well Gas Well X Other	065
2. Name of Operator	9. OGRID Number
MISSION RESOURCES CORPORATION	148381
3. Address of Operator <u>1331 LAMAR, SUITE 1455 HOUSTON, TEXAS 77010-3039</u> 4. Well Location	10. Pool name or Wildcat JALMAT; TAN, YATES, 7-RVRS(GAS) 79240
Unit Letter D feet from the NORTH line and	760 feet from the WEST line
Section 23 Township 23S Range 36E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, e 3365'GR	etc.)
Pit or Below-grade Tank Application or Closure	
Pit type <u>n/a</u> Depth to Groundwater <u>149</u> Distance from nearest fresh water well <u>1000'+</u> D	Sister of from mount out on the mount of the second s
500	
Pit Liner Thickness: n/a mil Below-Grade Tank: Volume _500_bbls; Construct	tion Material <u>object (In de Fundo)</u>
12. Check Appropriate Box to Indicate Nature of Notice	
	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER:	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D ve pertinent dates, including estimated date
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D ve pertinent dates, including estimated date
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion.	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'.	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic.	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Frac'd w/70% foam & 300,490# Prop.	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic.	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Frac'd w/70% foam & 300,490# Prop. Well produced 0 BOPD, 0 BWPD, 190 MCFPD, w/FCP 30 psig.	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OTHER: 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Frac'd w/70% foam & 300,490# Prop. Well produced 0 BOPD, 0 BWPD, 190 MCFPD, w/FCP 30 psig. Wellbore Schematic Enclosed. I hereby certify that the information above is true and complete to the best of my knowledge	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Frac'd w/70% foam & 300,490# Prop. Wellbore Schematic Enclosed. Wellbore Schematic Enclosed.	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT ve pertinent dates, including estimated date ch wellbore diagram of proposed completion ge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Frac'd w/70% foam & 300,490# Prop. Well produced 0 BOPD, 0 BWPD, 190 MCFPD, w/FCP 30 psig. Wellbore Schematic Enclosed. Intereby certify that the information above is true and complete to the best of my knowledger and take has been/will propositiveted or closed according to NMOCD guidelines, a general permit SIGNATURE TITLE	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D ve pertinent dates, including estimated date wellbore diagram of proposed completion estimated belief. I further certify that any pit or below- t [] or an (attached) alternative OCD-approved plan tory Tech DATE 07/07/05
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Frac'd w/70% foam & 300,490# Prop. Well produced 0 BOPD, 0 BWPD, 190 MCFPD, w/FCP 30 psig. Wellbore Schematic Enclosed. Intereby certify that the information above is true and complete to the best of my knowledger and take has been/will propositiveted or closed according to NMOCD guidelines, a general permit SIGNATURE TITLE	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT ve pertinent dates, including estimated date ch wellbore diagram of proposed completion ge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Added perforations (6 holes), 190 MCFPD, w/FCP 30 psig. Wellbore Schematic Enclosed. Thereby certify that the information above is true and complete to the best of my knowledger grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permited SIGNATURE TITLE Regula a E-mail address: Type or print name Valorie J. Garza	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT O ve pertinent dates, including estimated date the wellbore diagram of proposed completion ve pertinent dates, including estimated date the wellbore diagram of proposed completion ge and belief. I further certify that any pit or below- t [] or an (attached) alternative OCD-approved plan tory Tech DATE 07/07/05 valor ie. garza@mrcorp. com Telephone No. 713-495-3104
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 1/05 Added perforations (6 holes) in Tansill from 2580'-2936'. Added perforations (30 holes) in 7 Rvrs from 3162'-3408'. Details on Schematic. Acidized new perfs. Frac'd w/70% foam & 300,490# Prop. Well produced 0 BOPD, 0 BWPD, 190 MCFPD, w/FCP 30 psig. Wellbore Schematic Enclosed. Thereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permi SIGNATURE	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT O ve pertinent dates, including estimated date the wellbore diagram of proposed completion ve pertinent dates, including estimated date the wellbore diagram of proposed completion ge and belief. I further certify that any pit or below- t [] or an (attached) alternative OCD-approved plan tory Tech DATE 07/07/05 valor ie. garza@mrcorp. com Telephone No. 713-495-3104



X Well File

X OCD File