New Mexico Oil Conservation Division, District I 1625 N. French Drive

Form 3160-5 (August 1999) UNITED STATES Hobbs, NM 85240

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

,,	J	u	1	а	1	1	٦	v	•		
		A	ı	R	A	٨	ŧ	۸	A	ΩA	4

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use thi abandoned wel	Ī	If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No.					
SUBMIT IN TRI							
f. Type of Well Gas Well Oth	ner				8. Well Name and No SHOOT 12 FEDERAL #02		
2. Name of Operator HARVEY E. YATES COMPANY	Contact:	JEN ATKINSON		Ì	9. API Well No. 30)-025-30951	
3a. Address PO BOX 1933, ROSWELL, NM 8	8202-1933	3b. Phone No. (inc.)	clude area code) 5)623-6601)	10. Field and Pool, or Exploratory CORBIN DELAWARE West		
4. Location of Well(Footage, Sec., T., R., M., or S 420' FSL & 990' FEL SE	urvey Description ISE SEC 12 T 18S R 32	E			11. County or Parish, a	COUNTY, NM	
12. CHECK APPROPRIA	TE BOX(ES) TO INDIC	ATE NATURE	OF NOTICE	E, REPORT, (OR OTHER DA	ATA	
TYPE OF SUBMISSION	,	TYPE OF ACTION					
☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture ☐ New Co ☐ Plug and ☐ Plug Ba	nstruction d Abandon	☐ Reclama	lete arily Abandon S	Water Shut-Off Well Integrity Other QUEEZE PERFS, DRILL OUT IBP, ACDZ EXISTING PERFS	
 CHECK ANCHORS, HW SQUEEZE PERFS AT 49 DRILL OUT CEMT & TES TEST TBG TO 6000# TO DOWN PERFS & FOLLO SWAB TEST TO RECOV GIH W/RBP TO 7200', SE SWAB TEST. POOH W/TBG & PKR. G PRODUCTION. 	d operations. If the operation respondonment Notices shall be file inal inspection.) DWING WORK (SQZ PERFS) RODS & TBG. MIRU & POOL 43 - 51' TO 3000#. UNSET PET SQUEEZE TO 1000#. IF C 8900'. PICKLE TBG W/500 CW WITH 2000 GALLONS SAER LOAD. POOH W/TBG & T PKR @ 7100' & TEST RBF	ults in a multiple cond only after all requi- 4943-51', DRILL C H W/RODS & TBG KR & REVERSE C DK, DRILL OUT CI GALS 15% HCI NE ME ACID & 44 BA PKR.	mpletion or receirements, included OUT CIBP & A. SET PKR @ CMT IN TBG T MT & CIBP @ FFE ACID. SPI LL SEALERS.	ompletion in a n ling reclamation CIDIZE EXIST 2 4890' & TEST TO PIT. 6900'. TAKE TOT ACID ACRI TOTAL ACID	ew interval, a Form, have been completed in the property of th	3160-4 shall be filed once ted, and the operator has 994-98 & 8854-96 2 3 3 1 4-96 . BREAR	
14. I hereby certify that the foregoing is Name(Printed/Typed) JEN ATKI	Tit	Title PROD ANALYST		APL	0.0.0005		
Signature Sen all	Eiron	Da	7/1	5/05		BY GOURLEY	
	THIS SPACE FO	R FEDERAL (OR STATE	OFFICE US	SE PETRO	DLEUM ENGINEER	
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equal to	ed. Approval of this notice does	not warrant or	itle		,	Date	
which would entitle the applicant to conduct the same and the states any false, fictitious or fraudulent	U.S.C. Section 1212, make it a	crime for any person	office h knowingly and	d willfully to ma	ke to any departmen	nt or agency of the United	