## New Mexico Oli Conservation Division, District I 1625 N. French Drive Hobbs, NM-88240

FORM APPROVED **UNITED STATES** Form 3160-5 OMB No. 1004-0135 (September 2001) DEPARTMENT OF THE INTERIOR Expires January 31, 2004 BUREAU OF LAND MANAGEMENT 5. Lease Serial No. NMNM92771 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side Type of Well 8. Well Name and No. Oil Well Gas Well Other WBP FEDERAL #1 Name of Operator 9. API Well No. MARBOB ENERGY CORPORATION 3b. Phone No. (include area code) 30-025-35296 3a. Address 10. Field and Pool, or Exploratory Area ARTESIA, NM 88211-0227 (505) 748-3303 PO BOX 227, Location of Well (Footage, Sec., T., R., M., or Survey Description) LUSK: BONE SPRING 11. County or Parish, State 4567 LEA CO. 660 FSL 660 FWL, SEC.8-T19S-R32E, UNIT M 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Production (Start/Resume) Deepen Acidize Well integrity Reclamation Fracture Treat Notice of Intent Alter Casing Other Recomplete New Construction Casing Repair ☐ Subsequent Report Temporarily Abandon Plug and Abandon Change Plans ☐ Plug Back Water Disposal Final Abandonment Notice Convert to Injection Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. Describe rioposed of Completed Operation (clearly state an perturbin destails, including california stating date of any proposed work and approximate duration increof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertirent markers and zones. It the proposal is to deepen uncertainty of recomplete nonzonany, give subsulface locations and measured and the vertical depuis of an perment markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Attach the bond under which the work with the perfections of provide the bond two on the wint believes. Required subsequent reports shall be filled once following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filled once testing has been completed. Final Abandonment Notices shall be filled only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) MARBOB ENERGY CORPORATION PROPOSES TO ADD PAY IN THE BONE SPRING AS FOLLOWS: PERF THE UPPER BONE SPRING DOLOMITE @8054' - 8066' (13 SHOTS). SWAB TEST. ACIDIZE W/ 1500 GAL NEFE 20% HCL ACID. SWAB/FLOW TEST. SQZ/W/ 150-200 SX-"H" NEAT. .1111 2 6 2005 GARY GOURLEY PETROLEUM ENGINEER I hereby certify that the foregoing is true and correct Name (Rrinted/Typed) Title PRODUCTION ANALYST BRIGGS Date JULY 19, 2005 Signature FOR FEDERAL OR STATE OFFICE USE THIS SPACE Date Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.