New Mexico Oil Conservation Division, District I

1625 N. French Drive Hobbs, NM 88246 FORM APPROVED OM B No. 1004-0137

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Expires: March 31
Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

NM-058678				
6.	If Indian, Allottee or Tribe Name			

SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well Oil Well	14-08-0001-14277 8. Well Name and No.						
2. Name of Operator GRAMA RII	GRM UNIT #4 9. API Well No.						
3a. Address 3b. Phone No. (include area code) 20333 STATE HWY. 249, SUITE 400, HOU., TX 77070 281 374-3050					30-025-21334 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					GRAMA RIDGE MORROW		
2310' FNL & 2310' FWL F-4-22S-34E				11. County or Parish, State			
				LEA CO	UNTY, NEW MEXICO		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF ACTION							
✓ Notice of Intent Subsequent Report Final Abandonment Notice	✓ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (Star Reclamation Recomplete Temporarily Abo	. [Water Shut-Off Well Integrity Other		
13. Describe Proposed or Complete	Convert to Injection ed Operation (clearly state all per	Plug Back rtinent details, including estir	Mater Disposal mated starting date of an	y proposed work	and approximate duration thereof.		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.							

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be seed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160, shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Pursuant to USGS - "Agreement for Subsurface Storage of Gas, Morrow Formation, Grama Ridge Area, Lea County, New Mexico, "No. 14-08-0001-14277", the following is planned work of the GRM #4. Post workover plans pending approval are to utilize the well as a Injection and Withrawal well.

- 1. MIRU workover rig, NU and test BOP's.
- 2. POOH with production tubing and pickup work string.
- 3. GIH with work string and fish out existing completion.
- 4. Run CBL and casing inspection logs.
- 5. Reperforate and refrac exsisting Morrow completion.
- 6. Run production, ND BOP's and NU Tree.
- 7. RDMO workover rig.

Bond number on file with the BLM/BIA is NMB000304.

SUBJECT TO LIKE APPROVAL BY NMOCD

AUG 1 1 2005 **GARY GOURLEY** PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1						
RUDY SPITZENBERGER	NBERGER Title SR. PRODUCTION TECHNOLOGIST		OGIST				
Signature RE Spitzenberch	Date	08/05/2005					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by		Title	Date				
Conditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject less which would entitle the applicant to conduct operations thereon.	Office X2						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

(Instructions on page 2)