Office Office	State of New Me		Form C-103
District I E	nergy, Minerals and Natu		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		4 1 21 2 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0-025-36036
<u>District III</u> 1220 South St. Francis Dr.		ncis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		7505	STATE K FEE 5. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	2 4, 1 1, 1		o. State Off & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lea			1. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)			Hampton 1
1. Type of Well:			
Oil Well Gas Well S Other			
2. Name of Operator			B. Well No.
Chesapeake Operating, Inc. 3. Address of Operator			1 Declarate William I della CO
P. O. Box 18496, Oklahoma City, OK 73154-0496			Pool name or Wildcat Wildcol Norrow
4. Well Location			
Unit Letter N : 66	Ofeet from the South	n line and 205	0 feet from the West line
1	150		
Section 1	Township ^{15S} R	ange ^{35E} h	NMPM Le County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
GR: 3966.7 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENT		1	EQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG	S AND ABANDON 🔲	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON CHAN	IGE PLANS	COMMENCE DRILL	ING OPNS. □ PLUG AND □
	.0218410	OOMMENOE BINEE	ABANDONMENT
PULL OR ALTER CASING MULT		CASING TEST AND	
COMI	PLETION	CEMENT JOB	
OTHER:	П	OTHER: 5-1/2" c	sg, Rlse Rig, Perf, lst sa le
12. Describe proposed or completed operat	-	1	
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompilation.			
12/19/02 Run 322 jts 5-1/2" 17#-20# L-80 LTC csg, RU cmt crew, cmt w/35:65 Poz C1. H, tail			
w/545 sx Cl. C, bump plug, check float, open DV tool, circ 90 bbls cmt to surface			
12/20/02 Cmt 2nd stg w/490 sx 35:65 Poz + additives, tail w/100 sx Cl. H Neat, plug down,			
RD cmt crew, ND BOP, set slips, cut off, finish ND BOP, NU wellhead, install tree, clean			
	lg Rig #311 @12:00		
01/11/03 RU Schlumberger,			
02/06/03 RU Halliburton, pressure backside to 4500#, begin frac down tbg, pump 28,000 gal			
pad @14.3 BPM @9757#-10,450#, Stg 2 pump 7118 gal gel w/.5 PPG sand @14.8 BPM @9940#-10190#,			
Stg 3 pump 7252 gal gel w/l PPG sand @14.8 BPM @10340#-10556#, Stg 4 pump 9637 gal gel w/l			
PPG sand @14.9 BPM @ 10097#-10329#, Stg 5 pump 9065 gal Gel w/2.5 PPG sd @14.9 BPM			
@10596#-11008#, Stg 7 pump 1611 gal gel w/4 PPG sd @15.5 BPM @10551#-10907#, stg 8 pump 4046 gal flush @12.5 BPM @10072#-11324#, ISIP 5760#, 5 min 5770#, 10 min 5814#; 15 min 5845#			
RD Halliburton - total 6			
02/11/03 RIH w/60 jts 2-7/8			
<u> </u>	o Dynegy at 10:30 a	a.m.	// WAD - to
I hereby certify that the information above is	true and complete to the b	est of my knowledge a	1111
SIGNATURE BALLAL OR	. A mar p P.	egulatory Analys	St \S DAT#03/04/03
SIGNATURE Jarbara & B	IIILE K	egulatory Alialys	DATE DATE DATE DATE DATE DATE DATE DATE
Type or print name Barbara J. Bale			Telephone No. (405) 848-8000
(This space for State use)			
		ROLEUM ENGINEEP	APR 1 8 2003
APPPROVED BY	TITLET	KULLOW.	DATE
Conditions of approval, if any:			