

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**

P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.

30-025-09138

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

HALE WN

8. Well No.

1

9. Pool name or Wildcat

JALMAT TAN YATES SRQ GAS

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

BP America Production Company

3. Address of Operator

P.O. Box 1089 Eunice, NM 88231

4. Well Location

Unit Letter K : 1650 Feet From The S Line and 1650 Feet From The W Line

Section 34 Township 22S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3490' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 3594' OH 3144-3594'

Approved as to plugging of the Well Bore  
Liability under bond is retained until  
surface restoration is completed.

04.01.03: MIRUPU. NDWH. NUBOP.

04.02.03: RU tbg & tag cmt on top of CIBP @ 3045'. Press test CIBP to 300# psi. Held OK.

Circ hole w/9.5# mud to surf. POH w/tbg. RIH w/wireline & perf @ 1480' POH.

RIH w/pkr & tbg. Set pkr @ 1252'. Squeeze 50 sxs cmt. WOC.

04.03.03: POH w/pkr & tbg. RIH w/tbg & tag plug @ 1358'. POH. NDBOP. Leave 2 jts. & circ

10 sxs cmt from 60' to surf. POH. RDP. Cut off wellhead and dead man markers.

Clean location. Well P&A'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish

TITLE Sr. Administrative Assistant

DATE 04.15.03

TYPE OR PRINT NAME Kellie D. Murrish

TELEPHONE NO. 505.394.1649

(This space for State Use)

ORIGINAL SIGNED BY  
GARY W. WINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY

TITLE

DATE

APR 18 2003

CONDITIONS OF APPROVAL, IF ANY: